



Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 26May22

Address:

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 25 (Block 4)

Today's Date: 01Jun23

Contact(s): Sheshank Bhanuri - Cell: (647) 554-0700 - (sheshanksenu53@gmail.com)
Mounica Arugonda - Cell: (647) 972-3700 - (mounica.arugonda@gmail.com)

Email: sheshanksenu53@gmail.com

Company: Medi Group

Attention:

Telephone: (416) 741-2737

Fax: (416) 741-1593

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
157599	1 Year	Exterior- General- Item #3 loose mortar on porch in between seam at ledge		
157600	1 Year	Exterior- General- Item #4 area of missing mortar on porch		
157601	1 Year	Exterior- General- Item #5 gaps in mortar observed where the bricks meet the foundation at rear home below sliding door		
157606	1 Year	Exterior- General- Item #10 mortar splatter and stains on the window and frame - powerwash		
157612	1 Year	Exterior- General- Item #16 mortar splatter on the sliding door track powerwash		

06/05/23 *Jan*



MEDI GROUP Service

WO Number : **W-087403**WO Date : **01-Jun-2023**Issued To : **ROBERT ULJASZ**

Builder : Zancor

ZAN11

Project : ZANCOR-BROOKLIN TOWNS-3-21

Lot No : B4-25

Model :

Directions : Brooklin /Whitby
Intersection of Thickson Road and
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : Royal Gray

Main Stone :

Accent Brick :

Accent Stone : Light Grey (Chamfer Walling)

INIT	Item	Work Description	PO	Builder Ref #
<input checked="" type="checkbox"/>	1	LOOSE MORTAR ON PORCH IN BETWEEN SEAM AT LEDGE	<input type="checkbox"/>	B425JUN0123
<input checked="" type="checkbox"/>			<input type="checkbox"/>	S-068339
<input checked="" type="checkbox"/>	2	AREA OF MISSING MORTAR ON PORCH AND ON THE SIDES OF STEPS	<input type="checkbox"/>	B425JUN0123
<input checked="" type="checkbox"/>			<input type="checkbox"/>	S-068339
<input checked="" type="checkbox"/>	3	GAPS IN MORTAR OBSERVED WHERE THE BRICKS MEET THE FOUNDATION AT REAR HOME BELOW SLIDING DOOR	<input type="checkbox"/>	B425JUN0123
<input checked="" type="checkbox"/>			<input type="checkbox"/>	S-068339
<input checked="" type="checkbox"/>	4	MORTAR SPLATTER AND STAINS ON THE WINDOW AND FRAME- POWERWASH	<input type="checkbox"/>	B425JUN0123
<input checked="" type="checkbox"/>			<input type="checkbox"/>	S-068339
<input checked="" type="checkbox"/>	5	MORTAR SPLATTER ON THE SLIDING DOOR TRACK - POWER WASH <i>clean</i>	<input type="checkbox"/>	B425JUN0123
<input checked="" type="checkbox"/>			<input type="checkbox"/>	S-068339

02 June/23

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED JUN 05 2023