Enrollment:
Purchaser Name: Puneeta Skukla Phone Res: (647) 803-7318
Closing Date: June 15, 2023 Inspector: Gisella Fiore ANCO HOMES Page 1 of 2 Ū Municiapity: Inspection Date: Vendor / Builder: Project: Lot / Phase: Plan: Address: May 18, 2023 Zancor Homes (Caledon) Ltd. 122B / 1B

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
 Flooring (hardwood, vinyl, ceramic tiles, carpeting)
 Interior finished and trim carpentry

- Hot water heater, if provided (not rental) . Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door looks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided
 Electrical outlets and lixtures
 Gas fireplaces, incloirculation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system
 Howards in the system, if provided in the system is a system in the system.

Air conditioning system, if provided and if conditions permit

KITCHEN		,
CABINETS	CHIP AT UPPER GABLE ABOVE FRIDGE: 2) CHIP AT UPPER LEFT GABLE AT HOODFAN. 3) CHIP AT RIGHT LOWER GABLE RIGHT OF POT DRAWER AT EDGE BY DRYWALL AND FLOOR LINE AT KICKPLATE. 4) CHIP AT LEFT ISLAND GABLE AT FLOOR LINE FACING BREAKFAST. AND BY LEFT CABINET LEFT OF SINK. 5) CHIP AT RIGHT GABLE RIGHT OF HOODFAN.	· WILLE
NOTE:	UNABLE TO OPEN SLIDING DOOR AND CHIP AT BOTTOM LEFT MULIN OUTSIDE DOOR	0
MASTER ENSUITE BATH		,
VANITY CABINETS	CHIP INSIDE BOTTOM LEFT GABLE BELOW LEFT SINK	- DOTA
TUB	INSPECT BLACK MARK RIGHT SIDE OF TUB	Deno.
BEDROOM 3 ENSUITE		
VANITY CABINETS	CHIP AT BOTTOM RIGHT CABINET (INSIDE) BELOW SINK	200
FOYER/HALL		- 1
STAIRS	SMALL CHIP ON 1 AND 3RD TREAD AT STAIRS FROM MAIN TO 1ST LANDING TO 2ND FLOOR. CHIP ON NOSING AT ENTRANCE TO FOYER FROM FRONT DOOR 2) CHIP ON NOSING TO BASEMENT.	Sanc /
LIBRARY/DEN		
WALLS	CRACK / BUBBLE IN STIPPLE LEFT SIDE BY BACK WALL	Dane .
LAUNDRY ROOM		
CABINETS	CHIP IN SIDE UPPER RIGHT CABINET AT 2/3 SHELF 2) CHIP AT UPPPER RIGHT CABINET AT 4.8 BACK PANEL RIGHT OF SINK. 3) ADJUST LOWER LEFT CABINET LEFT OF SINK SITTING HIGHER	o Down
NOTE:	TRIM NOT INSTALLED BELOW NOSING AT LANDING TO LAUNDRY INSPECT NOSING AT LAUNDRY SLOPPED.	NA C
EXTERIOR		
PAINT	ROUGH PAINT ON FRONT DOOR. MOTAR MISUSING BELLOW SILL AT FRONT DOOR.	