Enrollment:

Purchaser Name: Prabhjot Kaur Jaura

Phone Res: Phone Bus:

Closing Date: July 10, 2023 Inspector: Alexandria Damianidis

ZANCOR

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd. Lot / Phase: 152B / 1B Plan:

Address:
Municlapility:
Inspection Date: June 23, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

- DAMAGED, INCOMPLETE OR MISSING

 Windows, side lights and other glazing. Window and door screens

 Bathtub sinks and tollets

 Bathroom accessories if provided

 Mirrors, counter tops and cathnetry

 Floring (hardwood, vinyl, ceramic tiles, carpeting)

 Interior finished and trim carpentry

- Furnace
 Hot water heater, if provided (not rental)

- OPERATING CONDITION

 Windows, interior and exterior doors. Door locks
 Faucets: Kitchen, bathroom, laundry room
 Exhaust fans (kitchen, bathrooms) if provided

 Electrical outlets and fixtures
 Gas tireplaces, incl.circulation fans, if provided
 Heat Recovery Ventilation system, if provided
 Heating system

 Hot water heater, if provided (not rental)

 Exterior finished, driv 	Exterior finished, driveways, walkways, decks and landscaping	 Air conditioning system, if provided and if conditions permi 	and if conditions permit		
EXTERIOR					
PORCH	SAW MARKS ON FRONT PORCH		NO	*	- 1
	FRONT POT LIGHT AS PER EXTRA SHOULD BE CENTRE OF ABOVE BALCONY ABOVE FRONT	RE OF ABOVE BALCONY ABOVE FRONT	さるが	2	
	PORCH				
NOTE:	BEMOVE MORTAR OFF REICK BIGHT SIDE OF HOUSE		7		

BOWNER BOOM		DENT	8Y NE	STAIRS SCRAT	FOYER/HALL	WINDOWS MULLIR	BEDROOM #3	CABINETS BOTTO	LAUNDRY ROOM	VANITY CABINETS CHIPS	MAIN BATHROOM	VANITY CABINETS SCRAT	FAUCETS/PLUMBING UPGRA	MASTER ENSUITE BATH	SINK/FAUCET/PLUMBING UPG	CABINETS CHIPS	KITCHEN	LENTI	CHIPP	NOTE: REMO	PORCH	PORCH	EXTERIOR
		DENT ON INSIDE STRINGER BY NOISING AT STAIRS TO FAR RIGHT SIDE AT STAIRS TO BSMT	BY NEWEL POST AT LANDING TO 2ND FLOOR	SCRATCH ON 2 AND 3RD PICKET AT STAIRS FROM MAIN TO LANDING TO 2ND AND 1ST PICKET		MULLIN DAMAGED		BOTTOMS OF ALL UPPER CABINETS BOWED		CHIPS ON BOTH SHELVES BELOW SINK		SCRATCH ON 2ND BANK OF DRAWERS	UPGRADED BATH ACCESSORIES NOT SUPPLIED THROUGH OUT		UPGRADED SOAP DISPENSER NOT INSTALLED, INSTAL WHERE GREEN TAPE IS	CHIPS AT BOTTOM GABLE AT FLOOR LINE AT ALL 3 PANELS		LENTIL NOT INSTALLED AT CORNER OF WINDOW LEFT OF FRONT PORCH	CHIPPED BRICK AT REAR OF HOME BELOW SLIDING DOOR	REMOVE MORTAR OFF BRICK RIGHT SIDE OF HOUSE	PORCH	SAW MARKS ON FRONT PORCH	
5	- Control of the Cont	20	-		5	NO		NO		NO	1	E	n SS		S	ON		NO.	0	NO	TOWNE	NO	
		Z	100	Ž	10	D.	10	X	2	7			Ì		A	2		1	Ž	2	4	3	2

