

Outstanding Deficiencies  
Reserve Of Country Trails - Phase: 1 - Lot: 2

| Date Reported | Type     | Number | Deficiency Description                                       | Trade Assigned                            | Add Trade | Appointment Date | Item Completed                      | Initial |
|---------------|----------|--------|--------------------------------------------------------------|-------------------------------------------|-----------|------------------|-------------------------------------|---------|
| 04 Aug 23     | Interval | 19     | Garage- General- Adjust /secure weather strip                | Abbey Overhead Doors Inc. 160678          | Add       | 25 Aug 23        |                                     |         |
| 04 Aug 23     | Interval | 20     | Kitchen- General- Svc to caulk crown molding -               | Zancor - Brampton Warranty Service 160679 | Add       | 25 Aug 23        | <input checked="" type="checkbox"/> | E-A     |
| 04 Aug 23     | Interval | 21     | Basement- General- Svc inspect insulation fallen in basement | Zancor - Brampton Warranty Service 160680 | Add       | 25 Aug 23        | <input checked="" type="checkbox"/> | E-A     |

Homeowner Signature: 

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Date: Aug 25/23

Zancor Service Technician: 