Enrollment:

Purchaser Name: Salwa KHAN

Faraz Ahmed SIDDIQUI

Phone Res: (917) 520-2361 Phone Bus: (917) 520-2362

Closing Date: October 26, 2023 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 404 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 404

Municiaplity:

Inspection Date: October 03, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		•	
CABINETS	CHIP AT FREEZER PANEL AND LEFT GABLE FRIDGE AT FLOOR LINE AND COUNTERTOP. 2) SCRATCH ON FRIDGE AT HANDLE.		
	SCRATCH ON FIRST AND SECOND BANK OF DRAWERS, RIGHT OF STOVE 2) CHIP AT UPPER GABLE TOP SHELF, LEFT A FRIDGE		
	CHIP ON LEFT STOVE PANEL RIGHT OF DISHWASHER CHIP AT THIRD SHELF IN UPPER CABINET LEFT A HOODFAN		
	MISSING SHELF IN LOWER LEFT CABINET LEFT OF SINK AND SCRATCH ON RIGHT CABINET DOOR		
LIVING ROOM			
WINDOWS	MULIN TRIM SHORT RIGHT OF WINDOW.		
	ADJUST SLIDING DOOR NOT LOCKING.		
WALLS	MISSING THERMOSTAT DRY WALLED OVER		
MASTER ENSUITE BATH			
COUNTERTOPS	CHIP ON COUNTERTOP INFRONT OF SINK.		
	CHIP JAMB AT BOTTOM AT ENTRANCE FROM DOOR		
MAIN BATHROOM			
VANITY CABINETS	SCRATCH INSIDE RIGHT CABINET BELOW SINK		
LAUNDRY ROOM			
FLOORING	LARGE CHIP AT TILE AT THRESHOLD.		

Enrollment:

Date (YYYY/MM/DD)

Purchaser Name: Salwa KHAN

Faraz Ahmed SIDDIQUI

Phone Res: (917) 520-2361 Phone Bus: (917) 520-2362 Closing Date: October 26, 2023 Inspector: Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 404 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 404

Municiaplity:

Inspection Date: October 03, 2023

Page 2 of 2

2023/10/03

A REFERENCE FOR FUTURE WARRA	NTY REQUESTS. designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHASE neir place should ensure they provide written autho	
I have inspected my new home and I a	agree that the description of the items listed	on this form are accurate.	
Salwa KHAN		Faraz Ahmed SIDDIQUI	
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
	gm	Gisella Fiore	Ibl
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature

October 03, 2023