Service @ Promark Aluminum Inc.

Gisella Fiore <Gisella@zancorhomes.com> January 11, 2022 2:03 PM

Sent:

From:

Subject: <u>ö</u>

Manfred Kerschbaumer; Service @ Promark Aluminum Inc.

Attachments: Eavestrough Sofit-Facia Gap (002).JPG Lot 134-1 Wasgaga- Promark

Good Afternoon,

Please find attached photo of the below sent to you today

Deficiencies on The Village of Trillium Forest - 3 - Block 134 Unit 1 For Promark Aluminum LTD.

WARRANTED-WILL INSPECT FOR GAP. $A/Lin2$	DAI 146648	Type 1	Issue Exterior- General- Item #13- eavestrough is bent at south west comer and also there is a gap between eaves and soffit - DENT NOT	Appt. Date / Time
Alliner	146648	Year	and also there is a gap between eaves and soffit - DENT NOT WARRANTED-WILL INSPECT FOR GAP.	
			Alliner	

Service Manager

Gisella exancomomes.com

P: 905.738.7010 F: 905.738.5948

221 North Rivermede Road- Concord, ON L4K 3N7

CONFIDENTIALITY NOTICE: This email message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please reply to the sender by email and destroy all copies of the original message.