Enrollment:

Purchaser Name: Mathiyaparanam KAMALANATHAN

Phone Res: (647) 404-3417

HOMES

Page 1 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 814 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 814

Municiaplity:

Inspection Date: October 31, 2023

Phone Bus: (647) 404-3417

Closing Date: November 10, 2023

Inspector: Alexandria Damianidis

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		•
CABINETS	ADJUST LOWER BANK OF DRAWERS	
	ADJUST UPPER CABINET LEFT OF SINK	
	SHELF NOT INSTALLED BELOW SINK RIGHT SIDE AND CHIP AT BOTTOM GABLE	
	REMOVE PROTECTIVE FILM FROM CABINETS THROUGHOUT	
	DENT AT UPPER CABINET ABOVE SINK	
POWDER ROOM		
ELECTRICAL/LIGHTIN	COVER PLATE MISSING - FOR ACCESS PANEL?	
WALLS	OVER CUT AT DRYWALL AT CEILING FAN	
FOYER/HALL		
CLOSET	OVER CUT/PAINT REQUIRED AT CEILING FAN IN FOYER CLOSET	
BEDROOM #2		
FLOORING	SHOE MOLDS NOT INSTALLED THROUGHOUT	
FAMILY ROOM		
WALLS	DRYWALL BULGE AT LEFT WALL	
	WALL VENT NOT INSTALLED	
LAUNDRY ROOM		
NOTE:	LINT TRAP NOT INSTALLED	
MASTER ENSUITE BATH		
NOTE:	PAINT REQUIRED IN CLOSET CEILING	
ELECTRICAL/LIGHTING	CAP NOT INSTALLED	
WALLS	HOMEOWNER UNHAPPY WITH GAP BETWEEN TILE AND DRYWALL AT SHOWER LEFT SIDE	
GENERAL COMMENTS		
NOTE:	REMOVE PAINT FROM FLOORS, LIGHT FIXTURES, LIGHT SWITCHES, DOOR HANDLES AND	
	HINGES AND OUTLETS THROUGHOUT	

Enrollment:

Purchaser Name: Mathiyaparanam KAMALANATHAN

ZANCOR

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 814 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 814

Municiaplity: Inspection Date: October 31, 2023

Phone Res: (647) 404-3417

Phone Bus:

Closing Date: November 10, 2023

Inspector: Alexandria Damianidis

MASTER BEDROOM

WALLS

OVER CUT AT SPRINKLER IN CLOSET

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. To designate someone to conduct the PDI in the	E HOME'S CONDITION BEFORE THE PURCHAS neir place should ensure they provide written auth	
	I agree that the description of the items listed	on this form are accurate.	
Mathiyaparanam KAMALANATHAN			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
	Chan		AD
	,,900	Alexandria Damianidis	14
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/10/31	October 31, 2023	