



IN-SERVICE Work Order

WO No: W-232442

WO Date: 01/23/2024

Contractor: RYAN WALL

Builder : ZANCOR HOMES

Project : R-ZAN523 - ZANCOR HOMES-INNISFIL-42'+1

Address : 1105 COLE STREET

City :

Contact :

Phone :

Cell:

Lot No: 357W

Model: 50-08

Block:

Phase:

Name:

Closing:

PDI Date:

Sch'd Date

Start Date

Comp Date

Unit Model

Serial No

02/06/2024

ML196UH090XE48C-19A

1723C48934

QTY

MATERIAL & WORK REQUIRED

SERIAL NO

HRV

- Screen installed in HRV Intake
- HRV wires (interlock) not connected due to steam humidifier being interlocked to Blower
- * Electrical cover missing inside HRV
- HRV Drain lines already installed
- Air leakage
- This is how manufacture builds cooling coils. Sealed Air leakage @ owners Request.
- Filter cover already Installed.

Airflow. New Airflow Readings

Corner Room Corner Room

55.60 70.75

- Airflow to Room was Reading o.h. Adjusted Airflow in House to Force more to Room

WO Notes :

@ owners Request.

** Please arrive 8-12

Call prior

(647)395-6786

- 167032 30-Day Exterior- General- Missing screen inside the HRV intake cover. ✓
- 167052 30-Day Basement- General- Missing cover inside the HRV. *
- 167053 30-Day Basement- General- Missing drain lines on the HRV. ✓
- 167054 30-Day Basement- General- Refrigerant lines not sealed at the furnace ✓
- 167055 30-Day Basement- General- AC drain not sealed on the furnace ✓
- 167056 30-Day Basement- General- Missing cover plate for the furnace filter. x
- 167057 30-Day Basement- General- HRV wires not connected inside the furnace x

Contractor

Invoice No

Invoice Amt

Date

Site Super Sign



Zancor Homes (Innisfil) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 08Sep23

Address: 1105 Cole Street
Innisfil, ON

Location: Belle Aire Shores - Phase: 3 - Lot: 357W

Today's Date: 19Jan24

Contact(s): Shankara, Nikhil Rachwani - Home: (647) 395-6786 - (nikhilesh786@outlook.com)
Manisha Singh - Home: (437) 229-0095 - (manisha.rachwani@outlook.com)

Email: nikhilesh786@outlook.com

Company: National Air

Attention: Ron Lochhead / Alex (Service)

Telephone: (416) 532-0654

Fax: (416) 532-3811

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
167032	30-Day	Exterior- General- Missing screen inside the HRV intake cover.		19Jan24 /am	
167054	30-Day	Basement- General- Refrigerant lines not sealed at the furnace		19Jan24 /am	
167057	30-Day	Basement- General- HRV wires not connected inside the furnace		19Jan24 /am	
167164	30-Day	Master Bedroom General- Poor airflow for both registers		19Jan24 /am	

Date Completed: Feb 6/24

Homeowner Signature: X SV

The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: Feb 6/24

Trade &/or Service Tech.

Signature: [Signature]

Print Name: [Name]