


February 19, 2009

Christina Persaud 3515 Kariya Drive 510 MISSISSAUGA ON L5B 0C1

Enrolment # H1512234 Case # 2356186



Tarion Warranty Corporation

Customer Centre 5150 Yonge Street, Concourse Level Toronto, Ontario M2N 6L8 Toll-Free: 1-877-982-7466

www.tarion.com

Copy to:

Amacon Development (Hurontario) Corp. 2 Harbour St. TORONTO Ontario M5J 3B1

Vendor/Builder # 33372 Lot: Pt. 16, Plan: , Block:

Mississauga, City

Confirmation of Receipt of your 30-Day Form

This notice is to inform you that we received your 30-Day Form and are accepting it based on the Date of Possession, January 19, 2009, of record for your home. Please note that this is the only 30-Day Form we can accept for your home, as outlined in the *Homeowner Information Package*.

All items noted on your 30-Day Form that are part of your unit and are covered by warranty under the Ontario New Home Warranties Plan Act ("statutory warranty") should be repaired or otherwise corrected by your builder by June 19, 2009, except as noted below*. If any of these items have not been corrected by this date, you may contact us between June 20, 2009 and July 20, 2009 to request a conciliation inspection of your home to assess the situation. If you do not contact us during this time period to request a conciliation inspection, we will consider all items listed on your 30-Day Form resolved and the matter closed. (You may resubmit the item(s) at a later date if the warranty covering those item(s) is still in effect.)

Because it can take several months for the natural materials in your home to dry and settle, new items may emerge over time. Your next opportunity to report to us any items that are covered by the statutory warranty occurs during the last 30 days before the first anniversary of possession of your home. During that period, you may report any such items by submitting the Year-End Form to us and sending a copy to your builder. (See your *Homeowner Information Package* for more details.)

The repair timelines listed above do not apply to items included in your condominium project's common elements because such items are not covered by your unit's statutory warranty. You should report these items in writing to the condominium corporation's Board of Directors. (For a complete description of your unit's boundaries, refer to Schedule "C" of the declaration of your condominium, which should be included with your Disclosure Statement.)

* Please note there are specific situations - such as emergencies and completion of your new home's landscaping - in which this timeline does not apply. Please refer to the *Homeowner Information Package* for more information about the Statutory Warranty Process and exceptions to it.

You may wish to visit our website to consult the *Construction Performance Guidelines*. The Guidelines describe many of the most commonly reported warranty items and indicate which are covered by warranty under the *Ontario New Home Warranties Plan Act*.

STATUTORY WARRAINTY FORE



30-Day Form

TO NOTIFY TARION OF OUTSTANDING WARRANTY ITEMS, COMPLETE AND SUBMIT THIS FORM BEFORE THE END OF THE FIRST 30 DAYS OF POSSESSION OF YOUR HOME.

YOU MAY SUBMIT ONLY ONE 30-DAY FORM.

| TO NOTIFY TARION OF OUTSTANDING WARRANTY ITEMS, COMPLETE AND SUBMIT THIS FORM BEFORE THE END OF THE FIRST 30 DAYS OF POSSESSION OF YOUR HOME. YOU MAY SUBMIT ONLY ONE 30-DAY FORM. | | | | | | |
|--|--|---|----------------------------|---|--|--|
| YOU MAY SUBMIT ONLY ONE 30-DAY FORM. | | | | | | |
| Submit this Form to the Tarion Customer Cent M2N 6L8, in person, by mail or courier, or by details about submitting this Form. <u>Send a co</u> Please print all information. | <u></u> | 10. See your F | tomeowner Informat | ion Package for | | |
| Home Identification Information (Refer to y | our Certificate of Comp | letion and Possess | ion to complete this ba | () | | |
| | NACON #333- for/Builder# | 12 | 1512234 Enrolment# | Re-(Co-) (Freely berger (Freely berger) | | |
| | | | | | | |
| 3515 KARNA DRIVE Street Number Street Name | The second section of the second section of the second second second second second second second second second | Late (See 1) See See Constitutives (See See) | 510 Condo Suite | # (d applicable) | | |
| MISSISS AUG A L | 58 OCI | Lat# | :Ama con | · · · · · · · · · · · · · · · · · · · | | |
| Contact information of Homeowner(s): | | • | Project/Subdivision | Name | | |
| CHRISTINA PERSOND Homeowner's Name (416) 838 - 7385 Daytime Phone Number | · | fornecwner's Nam | e (if applicable) | international control | | |
| (905) 232 - 2925 Evening Phone Number | CARE OF A CAME OF THE STATE OF | () | Trible | | | |
| () – Fax Number | ************************************** | () Fax Number | | | | |
| bestine 3 (2001) Com Email Address Check this box if you are not the original registered homeowner. | | | s box if you are not the o | nginal | | |
| Mailing Address for Correspondence to Homeowner (if different from Civic Address above) | | | | | | |
| Street Number Street Name | The state of the s | | | o Suite# plicable) | | |
| City/Town | Province: | Postal Co | de | | | |

PAGE: 003 OF 004

FROM: 4162369278

Outstanding Items

List all outstanding items covered by the statutory warranty in the table below. If you require more space, please make copies of this page, number them and attach them to this Statutory Warranty Form.

Outstanding items must be specifically listed and described.

A reference to the Pre-Delivery Inspection Form or to other documentation will not be accepted.

| ltem# | Room/Location | Description | | | |
|--|--|--|-----------------------|--|--|
| | Fourtentry | - Right 5th tile uneven gap at quarter munch. | 년 전 전 | | |
| 2 | Fayor tentry | Tile top left owner uneven gap at quarter round | H | | |
| 3 | Bathroom | holes in a grout in hullitub area | र्खात्र व | | |
| 4 | redmon | -2 drafts from middle window in bedroom | 당 | | |
| <u>5</u> . | bedroom | -Left Side of Indae of 1st and 2nd Window Oracked | RECTO C | | |
| 6 | Foyer | Santch in floor both tile in front of hedroom door | \ \ \ \ \ | | |
| 7 | Liting Room anna | -Hardwood flow Binks in front of Kitchen entrance | Q 2 | | |
| ₽ B | Litre Diriglan | Hardwood floor stratched 8th ward with back to | 西京技 | | |
| | J. J | sink in line with 3rd Window from left | <u>0</u> | | |
| 9 | frind brid bax | -Aluminium at base of and window 1st floor booked | 37.4 E | | |
| |), 0 | not flush with floor. | ig Cl | | |
| מב | Ling Dong lo | m-Facing window nght of last windows 8 | om or | | |
| | J. J. | - Inches up from floor point touch up | 픈 <u>향</u> | | |
| 11 | ال اسا | n Gullet in dining room (top one) not waring. | <u> </u> | | |
| 12 | | toth tile from front of bedroom door litting | 9-7-8 | | |
| 15 | 1 1, 1 | n-Crack in certing far right of patro door | Ę. | | |
| | i . | Windyan Colon Colo | 2 | | |
| 14 | <u> Tuving Omaglion</u> | togat in drintall and uneven drivall higher of | 877 | | |
| I Fayer Entry Right 5th tile uneven gap at quarter million. 2 Fayer Entry Right 5th tile uneven gap at quarter million. 3 Bothmarm holes in growt in hathitub area. 4 Bedroom a drafts from middle window in bedroom. 5 Bothmarm Left side of Indee of 1st and 2nd window areas. 6 Fayer Santch in flow out tile in front of bedroom down. 7 Liting bring from Hard wood flow sinks in front of vitanen entrance. 8 Wing Mining from Hard wood flow sinks in front of vitanen entrance. 9 Wing Mining from Aluminium at buse of and window from left. 9 Wing Dining from Aluminium at buse of and window 1st floor brand not flush with flow. 10 Listing Dining from Englet in dining room (top are) not working. 11 Wing Dining from Englet in dining room (top are) not working. 12 Fayer both tile from front of bedroom door lifting. 13 Wing Dining from Carlot in any for right of patro door. 14 Wing Dining from Carlot in any wat of a uncurn any will higher of patro door. 15 Wing Dining from Carlot in any wat of a uncurn any will higher of patro door. 16 Wing Dining from Carlot any wat of a uncurn any will higher of patro door. 17 Wing Dining from Carlot according to the step of all known warranty items which are outstanding and have not been resolved by my Builder to date. | | | | | |
| | | | | | |
| Homeowner's Signature (if applicable) | | | | | |
| Tomorpho, to contact the contact to contact the contac | | | | | |
| | SCOP 102-1/7 completed Form to your Builder. | | | | |

Please note that you should allow your Builder's representatives or subcontractors access to your home during regular business hours, at a mutually Please fight triat you should allow your colline a representation of account colline to do so may jeopordize your warranty rights.

TAIDM 2010/2010 02

For additional information a

PAGE: 084 OF 904

FROM: 4162369278. www arzan com

Outstanding items must be specifically listed and described.

A reference to the Pre-Delivery Inspection Form or to other documentation will not be accepted.

Outstanding Items

List all outstanding items covered by the statutory warranty in the table below. If you require more space, please make copies of this page, number them and attach them to this Statutory Warranty Form.

| item# | Room/Location | Description |
|----------|---------------------------------------|---|
| | | - Crack in ceiting left of biogress window |
| 160 | Deir | -Phone jack in non not warring |
| \7 | Bedroom | - outlet projee orong jack in treamoun arooked |
| 18 | Dining Room | - Phone jack in diving noom emoked |
| 19 | Living Diring Roo | - Phone jack in dining room enoked n - Hardwood floor lifting 10.1/h tile in line with |
| <u>-</u> | , , , , , , , , , , , , , , , , , , , | Kildren sirik |
| | | |
| } | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

The items specified on this Statutory Warranty Form constitute a complete list of all known warranty items which are outstanding and have not been resolved by my Builder to date.

Homeowier's Signature

102 111

Date of Signature (YYYY/MM/DD)

Homeowner's Signature (if applicable)

Remember to send a copy of this completed Form to your Builder.

Please note that you should allow your Builder's representatives, or subcontractors access to your home during regular business hows, at a multiality

TARN-30DY-04.02