

RECEIVED MAY 04/09
EVE 1209 5/0 CW
Scan to Pass

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: Diane Williams SUITE # 1209

DEVELOPMENT NAME: EVE ADDRESS: 3515 Kariya Dr

RES.TEL: 289 232-1430 BUS.TEL: 416 530 6056 CELL: 905 302 7668

FAX: _____ EMAIL: _____

DATE OF REQUEST: May 4, 2009

SERVICE REQUEST:

1. Heating Fan Coil unit not working in bedrooms. it does
2. not seem to be receiving any power. I checked fuse/circuit
3. but that wasn't it
4. _____
5. I give you permission to enter my suite.
6. _____
7. _____
8. _____
9. [Signature]
10. _____