

eve 905
scan to Pass

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

Rahul & Shikha Sharma.

NAME: Kannon Pothepennel (owner) SUITE # 905

DEVELOPMENT NAME: Ave Condes ADDRESS: 3515 Kariya Drive.

RES. TEL: 416 300 2777 BUS. TEL: 905 415 1250 CELL: 416-300-2777

FAX: _____ EMAIL: _____

DATE OF REQUEST: March 30th 2009

SERVICE REQUEST:

plug points + cable points closest washer in 2nd bedroom.
Crack in Onsuite Bathroom Mirror.

? exhaust fans in outside washroom + Onsuite Washrooms are
up to code? If you switch one on or off the other
temporarily turn on/off.

- to enter to closet work
hampers

evc 905
scan to Pass

AMACON SERVICE REQUEST FORM
PLEASE MAIL, FAX OR SUBMIT ON-LINE
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE
2 HARBOUR STREET, TORONTO, ON M5J 3B1
TEL: 416-369-9069 FAX: 416-369-9068
www.amacon.com

NAME: Dr. P. Kannen.

DEVELOPMENT NAME: _____

ADDRESS: # 905 3515 Konya Drive.

RES.TEL: 905-819-8087 BUS.TEL: 905-848-6212

CELL: 416-841-5812 FAX: 905-848-6867.

DATE OF REQUEST: Jan 27th 2009

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. Both Bedrooms plug points no supply
- Not working.
 2. _____
 3. _____
 4. Coorlet
- DONE**
Done - rofen

eve 905
scan to pass

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5J3B1

TEL: 416-369-9069 FAX: 416-369-9068

ATTENTION CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-848-2069 FAX: 905-848-2827

NAME: Kannan Pethesweral SUITE # 905

DEVELOPMENT NAME: Eve Condes ADDRESS: 3505 Kariya Drive

RES.TEL: _____ BUS.TEL: _____ CELL: 416 341 5812

FAX: _____ EMAIL: Kannan.pethesweral@yahoo.com

DATE OF REQUEST: April 7th 2009

SERVICE REQUEST:

- ✓ 1. plug ports in both bedroom: does not work.
- ✓ 2. Crack in Mirror On suite washroom.
- ✓ 3. Exhaust fan works and get off when you on the outside washroom.
4. _____
5. _____
6. _____
7. _____
8. _____
9. _____
10. _____

I give permission to enter suite to do work
Kannan Pethesweral

ave 905
scan to Pass

AMACON SERVICE REQUEST FORM
PLEASE MAIL, FAX OR SUBMIT ON-LINE
AMACON CONSTRUCTION LTD. ATTENTION: CUSTOMER CARE
2 HARBOUR STREET, TORONTO, ON M5J 3B1
TEL: 416-369-9069 FAX: 416-369-9068
www.amacon.com

NAME: Kannan pethaperumal

DEVELOPMENT NAME: _____

ADDRESS: 3515 Kariya Drive # 905

RES.TEL: 416 841 5812 BUS.TEL: 905 848 6212

CELL: 416 841 5812 FAX: 905 848-6867

DATE OF REQUEST: March 10 2009

A copy of your request form will be given to and reviewed by an Amacon Customer Care Representative. Your request and any follow up that may be required will be co-ordinated by one of our Customer Care Representatives to ensure that your concerns are addressed.

Service Request:

1. Room M Locker 225.
clips to the padlock has to be welded onto the door
2. Phenylene
3. Complete
4. _____

I Authorised to go into locker room to do the work.
hampel