

RECEIVED
H

for May 27/10

AMACON DEVELOPMENT

AMACON SERVICE REQUEST FORM

PLEASE MAIL, FAX OR SUBMIT ON-LINE

AMACON CONSTRUCTION LTD.

2 HARBOUR STREET, TORONTO, ON M5S 1B2

TEL: 416-363-3000 FAX: 416-363-3000
905-232-4437 (For Amacón)

905-232-4436

CUSTOMER CARE

ATTENTION: CUSTOMER CARE: 3515 KARIYA DR.

TEL: 905-846-2086 FAX: 905-846-2027

NAME: IORA QAZI

DATE: 2508

DEVELOPMENT NAME: Amacón

ADDRESS: 3515 Kariya Dr.

NOTE: 647-2102107

NOTE:

NOTE:

TEL:

EMAIL:

DATE OF REQUEST:

SERVICE REQUEST:

1. The water flow is not good at this suit.
2. No hot water for 15/20 mins. No cold water mostly.
3. Water flow in dishwasher low. If something happens to the appliances, Amacón is responsible.
4. I have kept complaining about plumbing water. This seems to be a never-ending problem in the building. Also fix the hallway lights please.
5. IORA - 647-210-2107
- 6.
- 7.
- 8.
- 9.
- 10.

Suit Entry Authorization

P.S. Spoke to
IORA on May 27
@ 8:26 AM
Advised her of
Transfer of Responsibility.
Building is already
FA in full control
By P.M.