

Consulting Engineers Peel Standard Condominium Corporation No. 889

Suite Performance Resident / Owner Questionnaire

The Board of Director's and Property Managers of your Condominium Corporation have retained Belanger Engineering to assess the condition of the common elements at this development. Your assistance in answering this questionnaire is needed to establish the extent and nature of any suite and any development performance related

problems that should have been resolved to date. So please take some time to observe, and recall, what is happened in your suite during various weather conditions.	or has
In order for us to include any performance related problems of the common elements in the second year we claim, please complete this questionnaire and return it to your condominium manager, Ms. Danielle Casha management office, by Tuesday September 25, 2012 . Additional comments, including concerns you may ha your balcony/terrace (if applicable), parking garage, etc., may be made on the back of this questionnaire.	in the
Name: Je Muroz Suite Number: 810 Address: 3525 KARIYA DN.	
1. Have there been repairs completed on the exterior and/or interior of your suite? Yes If so, please describe the nature and extent of repairs carried out.	0)
2a) Does water leak into your suite? If so, which room(s) and at what level (floor, ceiling, or around windows)? Yes	8)
b) Approximately, when was the last date water leaked into your suite?	
c) Does water leakage occur shortly after periods of rain <u>or</u> on warm, sunny days in the win spring?	nter or
3. Do you have black mildew on your ceilings or walls? If so, where? Yes	<u></u>
Thank you for your participation.	
1037234 Ontario Limited, O/A. Belanger Engineering	