



CONSTRUCTION SUMMARY

65 - 1 - The Golden Eye 2 (S48-2) Elev B

Extras at Time of Sale

Note:

ELECTRICAL

Inv.2,065	1 - EXTRA INERIOR CEILING OUTLET ROUGH IN NO FIXTURE ON NEW SWITCH
Line20808	Note:
1Dec17 / 4Jun18	
Inv.2,065	2 - EXTRA INERIOR CEILING OUTLET ROUGH IN NO FIXTURE ON EXISTING SWITCH
Line20809	Note:
1Dec17 / 4Jun18	

HARDWOOD FLOORING

Inv.2,065	1 - HARDWOOD FLOORING - STANDARD SERIES - 2 1/4 MERCIER SOLID OAK - LANDING - UPPER
Line20810	Note:
1Dec17 / 4Jun18	

CONSTRUCTION - STRUCTURAL CHANGES


Inv.2,065	1 - ENSUITE - GLASS DOOR - GLASS FROM WALL TO WALL AT FRONT OF SHOWER PLUS HALF GLASS PANEL OVER RIGHT SIDE OF SHOWER
Line20811	Note:
1Dec17 / 4Jun18	

STAIRS AND RAILINGS / NOSINGS

Inv.2,065	1 - UPGRADE RAILING - UPGRADE 1 - WROUGHT IRON
Line20812	Note:
1Dec17 / 4Jun18	


Alconia
SHORES

THE GOLDENEY




Goldeneye 2
Elev. B

YE 2 | SQ. FT. 3284 3274 | SINGLE 48 ft.
 Elevation A Elevation B




Goldeneye 2
 Elev. B


SECOND FLOOR



GROUND FLOOR
ELEVATION A




GROUND FLOOR
ELEVATION B




SECOND FLOOR


Goldeneye 2
Elev. B.



SECOND FLOOR
ELEVATION A



BASEMENT
ELEVATION B



~~BASEMENT~~
~~ELEVATION A~~