

# **CONSTRUCTION SUMMARY**

# Block 158 Unit 5 - 1 - The Napa 1 (TH-1) Elev A

# **Extras at Time of Sale**

	Note:					
--	-------	--	--	--	--	--

## **CEILINGS**

Inv.55	1 - SMOOTH CEILINS ON MAIN FLOOR
Line511	Note:
12Ian21 / 25Ian21	

## **CONSTRUCTION**

Inv.55	1 - ROUGH IN GARAGE DOOR IF GRADE DOES NOT PERMIT
Line513	Note:
12Jan21 / 25Jan21	

## **ELECTRICAL**

Inv.55	<b>1 -</b> ELECTRICAL - EXTRA INTERIOR CEILING OUTLET ROUGH-IN - NO FIXTURE - ON EXISTING SWITCH
Line <b>549</b>	Note: ABOVE BREAKFAST BAR - AS PER SKETCH
12Jan21 / 25Jan21	
Inv.55	<b>1 -</b> ELECTRICAL - EXTRA INTERIOR CEILING OUTLET ROUGH-IN - NO FIXTURE - ON NEW SWITCH
Line <b>514</b>	Note: ABOVE BREAKFAST BAR - AS PER SKETCH
12Jan21 / 25Jan21	

## **MISCELLANEOUS**


Inv. <b>57</b>	1 - 5 APPLIANCES - STAINLESS STEEL: FRIDGE, RANGE, DISHWASHER AND HOOD FAN – WHITE: WASHER AND DRYER. FROM VENDORS STANDARD LINE.
Line521	Note: AS PER BONUS
13Jan21 / 20Jan21	

Page 1 of 1

mmarySQL.rpt 13mar16 Printed and Sent: 25-Jan-21

DocuSign Envelope ID: D50AC422-3297-479D-A5EC-97AF3C867502

Black 158 Unit 5 Napa 1A




XSmooth ceilings on main Ploorx





Block 158 Unit 5 Napa 1A









Block 158 Unit 5 Napa 1A

