

Heathwood Homes (Huron) Limited

245 Yorkland Blvd., Suite 100 Toronto, Ontario M2J 4W9

Ship To

Ph: (416) 490-1400 Fax: (416) 490-1401 ** Pending **

PO# DE-UK-3-389-15595 Created: 08Dec22 Created By: Bei Liu

Approved By: Unauthorized Required Date: 08Dec22

Vendor

Ferjos Painting Corp. 1219 St. Clair Ave W, Suite U16 Toronto, Ontario

M6E 1B5

Ph: (416) 656-4414

Fax:

Reference

Re: Lot 389 Phase 3

Model: 25-2269 C The Walden

Site: Wallaceton

Quantity	Account	Description	Unit Price	Ext. Price
2.00	0704	FOYER AND MUD ROOM CLOSETS SKETCH # 2 - INTERIOR TRIM - UPGRADE FROM STANDARD 6 FT 8 INCH 2 PANEL HOLLOW CORE DOUBLE DOOR TO 8 FT 2 PANEL HOLLOW CORE DOUBLE DOOR - DRYWALL-Notify:FRAMING-Notify:PAINTING-Notify	\$0.00	\$0.00
1.00	0704	- HARDWOOD - VINTAGE - 3-1/4" RED OAK ENGINEERED - UPPER HALL - STANDARD SERIES - CARPET-delete std carpet: INTERIOR TRIM-supply and install quarter rounds: PAINTING- paint quarter rounds	\$60.00	\$60.00
1.00	0704	- DRYWALL - SMOOTH CEILING IN MAIN FLOOR - PAINTING-Notify	\$350.00	\$350.00
1.00	0704	SEE SKETCH # 2 - UPGRADE MAN DOOR FROM STANDARD 6 FT 8 INCH 8 FT 2 PANEL DOOR - DRYWALL-Notify:FRAMING-Notify:INTERIOR TRIM-Notify:PAINTING-Notify	\$0.00	\$0.00
2.00	0704	BASEMENT (REMOVED SEE REVISION) AND POWDER ROOM DOORS SKETCH # 2 - INTERIOR TRIM - UPGRADE FROM STANDARD 6 FT 8 INCH 2 PANEL HOLLOW CORE SINGLE DOOR TO 8 FT 2 PANEL HOLLOW CORE SINGLE DOOR - DRYWALL-Notify:FRAMING-Notify:PAINTING-paint upgraded door and frame	\$0.00	\$0.00
-1.00	0704	REVISION DELETE -UPGRADE FROM 6 FT 8 INCH DOOR 2 PANEL HOLLOW CORE SINGLE DOOR TO 8 FT 2 INCH PANEL HOLLOW CORE SINGLE DOOR IB UPPER BASEMENT STAIRS (NO SUFFICIENT HIGHT FOR 8 FT DOOR TO BE INSTALLED) SEE ORIGINAL SSS PAGE 4, SKETCH #2 - INTERIOR TRIM - UPGRADE FROM STANDARD 6 FT 8 INCH 2 PANEL HOLLOW CORE SINGLE DOOR -	\$0.00	\$0.00

\$410.00 Total:

Notes

- All above amounts are net of taxes.

- All invoices must quote a PO# and delivery address.
 All deliveries must be authorized by the site superintendent.
 All materials and/or work must comply with all applicable building codes and regulations.