

**Medi Group****PO Request**Request Date : **2022-10-24**PO Number: PO Date: **Builder :** Zancor **ZAN11**
Project : ZANCOR-BROOKLIN TOWNS-3-21**Lot No :** B4-21
Model :
Issued To :**Main Brick :** Royal Gray**Main Stone :** **Accent Brick :** **Accent Stone :** Light Grey (Chamfer Walling)**Code**
SO - WO**Work Description****9571**REPLACE BRICK AT R/S CORNER BELOW PORCH SLAB
NOTE: WAS HIT**S-065541****W-084210****PO Issued By** _____**Date** _____**PO Approved By** _____**Date** _____**Hours:** **Labour:** **Material:** **Total PO:**

Oct. 24/22

Ry.

MEDI GROUP

BLK 4- UNIT 21

FRONT:

- Replace brick at R/S corner below porch slab

***NOTE: ALL UNITS MUST BE PRESSURE WASHED**

OCT. 24/28 - 24.



Blk#4 Unit#21 front column remove 1 course of stone:



MEDI GROUP Service

WO Number : W-084210

WO Date : 20-Oct-2022

Issued To : ROBERT ULJASZ

Builder : Zancor

ZAN11

Lot No : B4-21

Project : ZANCOR-BROOKLIN TOWNS-3-21

Model :

Directions : Brooklin /Whitby

Intersection of Thickson Road and
Carnwith Drive (east of Thickson, north of

Address :

Contact :

Main Brick : Royal Gray

Main Stone :

Accent Brick :

Accent Stone : Light Grey (Chamfer Walling)

INIT	Item	Work Description	PO	Builder Ref #
☒	1	REPLACE BRICK AT R/S CORNER BELOW PORCH SLAB HIT	☒	ALLAUG0922
☒	2	FRONT COLUMN REMOVE 1 COURSE OF STONE - SEE PHOTO	☐	S-065541
			☐	08M101541
			☐	S-065545

21 Oct/22

Homeowner Signature

Date Completed

Site Super Signature

Date Completed

Special Notes :

COMPLETED OCT 24 2022