

①

X

Master ensuite 61B

. DAP TILE LINE TO WALL - ZAN

Zancor

Caledon

✓ 1-SHELF for 950-1000 Cabinet

✓ 1-SHELF for 1450 cab

. SILICONE NEEDED - AV

✓ 1-SHELF for B750 Island

Mo
July 25
Key

. STRIP LIGHT MISSING A BULB - AE

. ALIGN ALL CABINETS N.I

I want
PDI on process
"Apparently all
kitchen is wrong"

MASTER BEDROOM:

. RETURN AIR PLATE NOT FLUSH WITH
WALL NA / ZAN

. WALL ACROSS FROM WINDOW BOWED ZAN

X

MAIN BATH

. MISSING ONE LIGHT BULB DE,

. ALIGN CABINETS NI,

BED #2 ENSUITE:

. COUNTER TOP NOT TO WALL RS,

. ALIGN ALL CABINETS NI,

. DAP TILE LINE TO WALL ZAN

X

Powder Room

• EXHAUST FAN NOT WORKING N/A.

• CHIP IN CABINET LOWER GABLE NI

• SILICONE PLUMBING ZAN

KITCHEN:

• WIRE PROTRUDING FROM SLIDING DOOR
FRAME

• LEFT SIDE

P.H.

• SMALL CHIP IN SHELF ABOVE SINK NI

x
• CHIP IN SHELF LEFT OF COOK TOP
• LOWER
• CABINET NI

• SMALL CHIP IN DRAWER BELOW COOK
• TOP NI

• SMALL CHIP ABOVE COOK TOP NI

• PAINT UPPER GABLE SIDE ABOVE COOK
• TOP
• WHITE NI

• CHIP IN ISLAND SHELF RIGHT SIDE NI