

A M A C O N

L I V E W E L L

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 1102</u> <u>1102 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>15Dec08</u>
Contact Name(s)	<u>Michael Dawson and Andrea Flores</u>
Contact Telephone#	
Company:	<u>Barwood Flooring</u>
Attention:	
Telephone:	
Fax:	<u>(416) 431-2393</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:

Deficiency Number	Issue		Appointment Date/Time	Notes
1170 ✓	LIVING/DINING ROOM-FLOORING-T-CAP SCRATCHED at entry to den	✓		
1171 ✓	LIVING/DINING ROOM-FLOORING: 1-9, 10 11th, 13, 15, 16, 18, 20, 21 22, 26 board left of den in front of window scratched	✓		
1172 ✓	LIVING/DINING ROOM-FLOORING: 2-floorboards uneven/move 3 feet from balcony door	✓		
1173 ✓	LIVING/DINING ROOM-FLOORING: 3-scratch 10th board in front of island, boards also move/uneven	✓		
1174 ✓	LIVING/DINING ROOM-FLOORING: 4-movement boards 2 feetg from island gable	✓		
1175 ✓	LIVING/DINING ROOM-FLOORING: 5-scratch at left corner island gable	✓		
1176 ✓	LIVING/DINING ROOM-FLOORING: 6-CHIPPED board 3 board in front of pantry	✓		
1177 ✓	LIVING/DINING ROOM-FLOORING: 7-scratch 2nd board in	✓		

DEC 15, 2008

https://apps.prospectin.com/amacon/_builder/AMAServiceCall.php3?var_Centre=Eve&v... 12/15/2008

Remount

3

1/4

Round

Kariya