AMACON

Warranty Services Work Order

Phone: (905) 848-2069 Fax:(905) 848-2827

WELL LIVE

Eve - Tower: 1 - Unit: 503 503 - 3515 Kariya

Closing Date

Location

0000

Date

25Nov08

Contact Name(s)

Seweryn Horawa and Ayan Hussein

Contact Telephone#

Amacon Service

Company: Attention:

Carlos Bravo

Telephone:

<u>9 (05-) 848--282</u>

Fax: From:

Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number			Appointment Date/Time	Notes
231	GUEST BEDROOM 1- CLOSET- ADJUST doors n0t square			
235	MASTER BEDROOM- DOORS- DENTED by latch		×	
250	MAIN BATHROOM- COUNTERTOPS-CAULKING MISSING underside countertop	V		
254	ENSUITE BATHROOM- COUNTERTOPS-no silicone underside of countertop	V		
257	KITCHEN- COUNTERTOPS-silicone missing underside of countertop			
260	KITCHEN- COUNTERTOPS: 2-gap under counter with missing shims and silicone			
²⁶¹ \checkmark	KITCHEN- COUNTERTOPS: 3- LEVEL top drawer will not open properly		<i>y</i>	
263	KITCHEN- SINK-should be undermiunt			MAR AMACON
266	KITCHEN- APPLIANCE-FRIDGE LEVEL	2 market and a		
267 V	KITCHEN- BACKSPLASH-dab missing by fridge			

Date Completed: Dec. 1108

Purchaser Signature:

Furehaser acknowledges and accepts all work has been completed in a workmanlike manner.

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2877

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 231/235/250/254/257/260/261/263/266/267 Eve Ph 1 Lot 503

Mail