AMACON

LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 909
	T7 1

<u>909 - 3515 Kariya</u> <u>0000</u>

Closing Date

Date

15Dec08

Contact Name(s)

Yahya Alkhodari

Contact Telephone#

Company:

Barwood Flooring

Attention:

Telephone:

(416) 431-2393

Fax: From:

Warranty Services Department - Head Office

Deficiency	omplete the following items:		Appointment	Notes
Number			Date/Time	
956	LIVING/DINING ROOM- FLOORING-floors by large window paint and scratched -by den entry and balcony	and the state of t		
957	LIVING/DINING ROOM- FLOORING: 1-rightside by balcony entry 8 boards towards centre scratched - please check	d and a state of the state of t		
958	LIVING/DINING ROOM- FLOORING: 2-rightside by light switch 1' towards window 5 board scratched	V		
959	LIVING/DINING ROOM- FLOORING: 3-glue marks right of kitchen island 8 boards to centre of livingroom			
960	LIVING/DINING ROOM- FLOORING: 4-to right of fancoil boards 8 and 10 scratched	Jana		
961	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-ok	X		NOT BALWOOD
Date Co	ompleted: Ne 15, 0%	Purchas	er Signatu	re: Manual The Furchaser acknowledges and accepts all

https://apps.prospectin.com/amacon/_builder/AMAServiceCall.php3?var_Centre=Eve&v... 12/15/2008

Material -