



LIVE WELL

# Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<b><u>Eve - Tower: 1 - Unit: 1708</u></b> <b><u>1708 - 3515 Kariya</u></b>
<b>Closing Date</b>	<b><u>0000</u></b>
<b>Date</b>	<b><u>13Feb09</u></b>
<b>Contact Name(s)</b>	<b><u>Winston Santos</u></b>
<b>Contact Telephone#</b>	
<b>Company:</b>	<b><u>Kabinetz</u></b>
<b>Attention:</b>	<b><u>Paul Cammalleri</u></b>
<b>Telephone:</b>	
<b>Fax:</b>	
<b>From:</b>	<b><u>Warranty Services Department - Head Office</u></b>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
11162	MAIN BATHROOM-COUNTERTOPS-banjo countertop chipped right edge below light switch - see tape			
11163	MAIN BATHROOM-COUNTERTOPS: 1-red marks and caulking on banjo countertop -see tape			
11164	KITCHEN- CABINETS-kitchen gable top left corner chipped -see tape			
11165	KITCHEN- CABINETS: 1-kitchen gable right edge chipped -see tape			
11166	KITCHEN- CABINETS: 2-lazy susan cabinet gap -see tape			
11167	KITCHEN- CABINETS: 3-cabinet above fridge gap between doors -see tape			
11168	KITCHEN- CABINETS: 4-large lower cabinet left of fridge gap -see tape			
11169	KITCHEN- CABINETS: 5-corner upper panel scratched and black marks - see tape			

Date Completed:

FEBRUARY 13, 09

Amacon Customer Care Signature: