

A M A C O N

L I V E W E L L

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax:(905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 1808</u> <u>1808 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>13Feb09</u>
Contact Name(s)	<u>Maureen Lee Ah Yen and Edward Lee Ah Yen</u>
Contact Telephone#	
Company:	<u>Kabinetz</u>
Attention:	<u>Paul Cammalleri</u>
Telephone:	
Fax:	
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
11230	MAIN BATHROOM- COUNTERTOPS-banjo countertop chipped far left corner and also paint - see tape			
11232	KITCHEN- CABINETS-kickplate under sink not flush -see tape			
11233	KITCHEN- CABINETS: 1-lower cabinet frame bottom right of sink chipped -see tape			
11234	KITCHEN- CABINETS: 2-3rd drawer not aligned -see tape			
11235	KITCHEN- CABINETS: 3-upper cabinet right of stove scratched -see tape			
11236	KITCHEN- CABINETS: 4-kitchen island -facing window scratched -see tape			

Date Completed:

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service