



LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 3001</u> <u>3001 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>10Feb09</u>
Contact Name(s)	<u>Kamal Damouni and Yassmine Damouni</u>
Contact Telephone#	
Company:	<u>Barwood Flooring</u>
Attention:	
Telephone:	
Fax:	<u>(416) 431-2393</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
9760	LIVING/DINING ROOM-FLOORING-floor moves/buckles in front of windows			
9761	LIVING/DINING ROOM-FLOORING: 1-chip in board in front of fan coil unit, see tape			
9762	LIVING/DINING ROOM-FLOORING: 2-scuff marks and scratches in front of balcony door, see tape			CALL BARWOOD.
9763	LIVING/DINING ROOM-FLOORING: 3-scratches by work station, see tape			
9764	LIVING/DINING ROOM-FLOORING: 4-chip and scratches in front of island, see tape			
9765	LIVING/DINING ROOM-FLOORING: 5-scratches on T-CAP by foyer, see tape			

Date Completed:

FEBRUARY 10, 2009

Amacon Customer Care Signature: