



Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 3602</u> <u>3602 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>04Mar09</u>
Contact Name(s)	<u>Wing Hoi Leung and Kin Yee Leung</u>
Contact Telephone#	
Company:	<u>Barwood Flooring</u>
Attention:	
Telephone:	
Fax:	<u>(416) 431-2393</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
12540	LIVING/DINING ROOM- FLOORING- boards scuffed/scratched, see tape	✓		
12541	LIVING/DINING ROOM- FLOORING: 1- floor buckling in front of fanCOIL unit	✓		
12542	LIVING/DINING ROOM- FLOORING: 2- floor scratched in front of bathroom, see tape	✓		
12543	LIVING/DINING ROOM- FLOORING: 3- floor buckling in front of laundry closet	✓		

Date Completed:

MARCH 2 2009

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. **Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

[Back - Forms Menu](#)

ID# 12540/12541/12542/12543 Eve Ph 1 Lot 3602