AMACON

LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Eve - Tower: 1 - Unit: 1003 Location

0000

05Dec08

1003 - 3515 Kariya

Susan Dubrez-Carey

Closing Date Date

Contact Name(s)

Contact Telephone#

Company: Attention:

Amacon Service Carlos Bravo

Telephone: Fax:

From:

(905) 848-2827 Warranty Services Department - Head Office

Please complete the following items:						
Deficiency Number	Issue		Appointment Date/Time	Notes		
1019 🗸	FOYER / ENTRY- WALLS-right wall marked 3 feet frm floor 3 feet from entry door					
	DEN- WALLS-paint chipped 7 feet from floor left side entry		1			
1025	DEN- WALLS: 1-paint chipped 3 feet from floor right side entry		L			
1028	KITCHEN- CABINETS-centre post missing cabinet under sink			Kitcheis		
1030 🗸	KITCHEN- CABINETS: 1-rubber stopper missing in uppercabinets		* A STATE OF THE S			
1032	KITCHEN- CABINETS: 2- CABINET above fridge needs réalignment		Lorenteeder			
1034	KITCHEN- CABINETS: 3- CABINET right of microwave needs realignment		The state of the s	·		
1036 V	KITCHEN- CABINETS: 4- CABINET over fridge screws need adjustment underside of cabinet		Berther Burkey and			
1038	KITCHEN- CABINETS: 5-3rd draw sticks		Labor Market			
1040	KITCHEN- APPLIANCE-STOVE drawer does not slide properly		essential de la constantial del constantial de la constantial de la constantial de la constantial de la constantial del constantial de la			
1041	KITCHEN- APPLIANCE: 1-	Investagate				

	DISHWASHER top finishing plate missing		Plumer
1 i	MASTER BEDROOM- WALLS- DRYWALL rough right side of alarm silencer	1 control of the second	

Date Completed: Dec. 18/08 | Purchaser Signature:

The Purchaser acknowledges and accepts all work has been completed in a workmanlike manner.

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 1019/1024/1025/1028/1030/1032/1034/1036/1038/1040/1041/1539 Eve Ph 1 Lot 1003

Mail

https://24.84.33.103/exchange/pdimaria/Inbox/Eve%20-%20Tower:%201%20-%20Unit:%... 12/5/2008