



LIVE WELL

Warranty Services  
Work Order

Phone: (905) 848-2069 Fax:(905) 848-2827

Location	Eve - Tower: 1 - Unit: 1006
Closing Date	1006 - 3515 Kariya
Date	0000
Contact Name(s)	05Dec08
Contact Telephone#	Bernabe Lopez and Santa Lopez
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
1046 ✓	FOYER / ENTRY- DOORS-leftside of entry doorframe chipped top and bottom		✓	
1049 ✓	LIVING/DINING ROOM- WINDOWS-caulking above balcony doorframe needs to be cleaned		✓	
1051 ✓	MASTER BEDROOM- WINDOWS-space between window jamb and ceiling		-	Normal
1053 ✓	MAIN BATHROOM- VANITY CABINETS-top drawer panel needs to be attached		✓	
1055	ENSUITE BATHROOM- COUNTERTOPS-vanity counter top big chip by edge of sink			Kitchen
1057	ENSUITE BATHROOM- VANITY CABINETS-vanity cabinet door leftside door not opening			" "
1060	KITCHEN- CABINETS-bottom drawer rightside fridge needs adjusting			" "
1062 ✓	KITCHEN- CABINETS: 1-shelves missing in all cabinet		✓	
1064 ✓	KITCHEN- CABINETS: 2-rightside of microwave upper cabinets need adjusting		✓	