

**A M A C O N**

L I V E   W E L L

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 1007</u>
	<u>1007 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>19Dec08</u>
<b>Contact Name(s)</b>	<u>Erika Palladino and Ken Russell</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
1069	✓ FOYER / ENTRY- WALLS- DRYWALL REPAIR WHERE NOTED PATCH/PAINT LEFT OF DOOR 1FOOT OVER & DOWN FROM SOCKET		✓	
1077	✓ LIVING/DINING ROOM- WALLS-LEFT OF LAUNDRY CLOSET 2FEET OVER 3FEET UP SILICONE STUCK ON WALL & BLACK MARKS		✓	
1078	✓ LIVING/DINING ROOM- WALLS: 1-CHIPPED CORNER LEFT OF LAUNDRY CLOSET ON CORNER 3FEET UP FROM TILES		✓	
1083	✓ GUEST BEDROOM 1- CLOSET- DRYWALL DENTED LEFT OF DOOR 5FEET UP @ EDGE OF CLOSET		✓	
1085	MASTER BEDROOM- WALLS- CORNER RIGHT OF FIRE ALARM 2FEET FROM CARPET SILICONE NEEDS REMOVING		-	
1086	✓ MASTER BEDROOM- WALLS: 1-BULKHEAD RIGHT OF WINDOWS 4FEET BACK DENTED		✓	

1091	✓ MASTER BEDROOM- CEILING: 1-DRYWALL CRACKING 1FOOT LEFTOF MIDDLE WINDOWS		✓	
1092	✓ MASTER BEDROOM- CLOSET- RIGHTOF WASHROOM HOLE ABOVE WIRE SHELF REPAIR PAINT		✓	
1094	MASTER BEDROOM- WINDOWS-FRAME LAST PANE LEFT SIDE 2INCHES UP CUTS	Do not understand defecency explain please	—	
1096	MAIN BATHROOM- VANITY CABINETS-CABINET WALL BESIDE TOILET IS PURPLE ON OUTSIDE			Kitchen's
1099	✓ ENSUITE BATHROOM- COUNTERTOPS-RED GLUE ON COUNTER 3FEET FROM RIGHT AND 1FOOT FROM LEFT WALL		✓	
1101	ENSUITE BATHROOM- VANITY CABINETS-RIGHT WALL REVERSED WRONG SIDE OUT			Kitchen's
1104	✓ KITCHEN- CABINETS- CABINET LEFTOF MICROWAVE SHEVES MISSING BRACKETS		✓	
1106	✓ KITCHEN- CABINETS: 1- LEFTOF FRIGE TOP PARTS LEFT BEHIND		✓	
1108	KITCHEN- CABINETS: 2- DRAWER TOP NEEDS ALIGNMENT			Kitchen's
1109	KITCHEN- CABINETS: 3-3RD DRAWER NOT SMOOTHLY CLOSING			11 11
1112	✓ KITCHEN- CABINETS: 4-TOP CABINET ABOVE MICROWAVE RUBBING IN MIDDLE		✓	
1117	✓ LAUNDRY CLOSET- WALLS- WATER SHUT OFF GAP FROM WALL		✓	

Date Completed:

Dec 23/08

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID#

1069/1077/1078/1083/1085/1086/1091/1092/1094/1096/1099/1101/1104/1106/1108/1109/1112/1117  
Eve Ph 1 Lot 1007