

AMACON

LIVE WELL

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 1009
	1009 - 3515 Kariya
Closing Date	0000
Date	19Dec08
Contact Name(s)	Vangal Subramanyam
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
1121	✓ LIVING/DINING ROOM- WINDOWS-PATIO DOOR FRAME CAULKING MESSY & UNEVEN ALL AROUND		✓	
1126	✓ LIVING/DINING ROOM- WALLS- DRYWALL REPAIR PATCH/PAINT BELOW SOCKET RIGHT OF TELEPHONE JACK		✓	
1128	✓ GUEST BEDROOM 1- WALLS- DRYWALL SCRATCHED @ CABLE BOX ABOVE & RIGHT OF ABOVE SOCKET RIGHT OF CABLE BOX DRYWALL		✓	
1129	✓ GUEST BEDROOM 1- WALLS: 1- RIGHT OF FAN COIL 3 INCHES OVER FROM TOP & DOWN 2 FEET FROM CARPET		✓	
1131	✓ GUEST BEDROOM 1- WALLS: 2- BLACK MARKS 6 FEET UP LEFT OF SLIDING WINDOWS SMALL WALL		✓	
1132	✓ GUEST BEDROOM 1- WALLS: 3- DRYWALL DAMAGED 3RD PANE LOWER RIGHT OF 2 FEET FROM CARPET & 4 FEET		✓	
1137	MASTER BEDROOM- WALLS: 1-			

https://apps.prospectin.com/amacon/_builder/AMAServiceCall.php3?var_Centre=Eve&v... 12/19/2008

 1205
 12367 910

	✓ DRYWALL DENTED RIGHT OF WINDOWS 2 INCHES FROM FLOOR		✓	
1138	✓ MASTER BEDROOM- WALLS: 2- DRYWALL BUMP BETWEEN SOCKET & TELEPHONE JACK		✓	
1144	MAIN BATHROOM- COUNTERTOPS-CHIPPED CORNER LEFT OF TOILET PAPER HOLDER &			<i>Kitchen's</i>
1150	ENSUITE BATHROOM- COUNTERTOPS-ABOVE TOILET PAPER HOLDER TOWARDS MIRROR COUNTER TOP FACING COMING OFF			" "
1153	KITCHEN- CABINETS-CABINET LOWER RIGHT OF RANGE NOT HUNG & MISSING HARDWARE			" "
1155	KITCHEN- CABINETS: 1- BRACKETS MISSING TOP CABINET LEFT OF MICROWAVE			" "
1157	KITCHEN- CABINETS: 2-MISSING SHELVES LEFT OF FRIDGE TOP CABINET ONLY 2 IN BOTTOM CABINET			" "
1159	KITCHEN- CABINETS: 3- BRACKETS MISSING RIGHT OF MI			" "
1161	KITCHEN- COUNTERTOPS- ROWAVE			" "
1163	KITCHEN- COUNTERTOPS: 1- CHIPPED INSIDE DOORS TOP CANINETS 3RD DOOR & 4TH & 6TH			" "
1165	✓ KITCHEN- WALLS-EXCESS GAP BOTTOM OF SOCKET RIGHT OF FRIDGE		✓	

Date Completed:

Dec 15/08

Amacon Customer Care Signature:

[Signature]

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry