

LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

| | |
|---------------------------|---|
| Location | Eve - Tower: 1 - Unit: 1508 1508 - 3515 Kariya |
| Closing Date | 0000 |
| Date | 13Feb09 |
| Contact Name(s) | Tara Benson |
| Contact Telephone# | |
| Company: | Amacon Service |
| Attention: | Carlos Bravo |
| Telephone: | |
| Fax: | (905) 848-2827 |
| From: | Warranty Services Department - Head Office |


| Please complete the following items: | | | | |
|--------------------------------------|--|--|-----------------------|---------------|
| Deficiency Number | Issue | | Appointment Date/Time | Notes |
| 11029 ✓ | FOYER / ENTRY- WALLS-right wall drywall rough by light switch -see tape | | ✓ | |
| 11030 ✓ | FOYER / ENTRY- WALLS: 1-right upper corner above frame - chipped -see tape | | ✓ | |
| 11031 ✓ | FOYER / ENTRY- DOORS-inside door paint spots -see tape | | ✓ | |
| 11041 ✓ | LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil missing filter -see tape | | ✓ | |
| 11043 ✓ | LIVING/DINING ROOM- WINDOWS-slider lock scratched -see tape | | ✓ | |
| 11044 ✓ | LIVING/DINING ROOM- WINDOWS: 1-missing alUMINUM casing - right side of balcony doors -see tape | | ✓ | |
| 11045 ✓ | LIVING/DINING ROOM- WINDOWS: 2-balcony sill nail hole underneath -see tape | | ✓ | |
| 11046 ✓ | LIVING/DINING ROOM- WINDOWS: 3-balcony doorframe scratched -top and sides -see tape | | ✓ | |
| 11048 | LIVING/DINING ROOM- WINDOWS: 4-balcony window not put in properly - door dented -- major draft -see tape | | — | allow Windows |
| 11052 ✓ | MASTER BEDROOM- DOORS-mirror closet doors not opening well --see tape | | ✓ | |
| 11053 | MASTER BEDROOM- FLOORING-carpet stain by entry -see tape | | | |
| 11055 ✓ | MASTER BEDROOM- CEILING-cracked by left window near bulkhead -see tape | | ✓ | |

| | | | | |
|-------|---|--|---|--|
| 11058 | ✓ MASTER BEDROOM- WINDOWS- aluminum casing scratched -see tape | | ✓ | |
| 11059 | ✓ MASTER BEDROOM- WINDOWS: 1- balcony sill chipped underside -see tape | | ✓ | |
| 11060 | ✓ DEN- WALLS-chipped wall below light switch on left entry wall -see tape | | ✓ | |
| 11063 | ✓ MAIN BATHROOM- TUB-temperature control, faucet and showerhead need silicon - see tape | | ✓ | |
| 11067 | ✓ KITCHEN- APPLIANCE-stove scratched on top and left corner -see tape | | ✓ | |
| 11068 | ✓ KITCHEN- WALLS-bulkhead above microwave -nail pops -see tape | | ✓ | |

Date Completed:

Feb 14/09 18

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. **Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

Back -

Forms

Menu

ID#

11029/11030/11031/11041/11043/11044/11045/11046/11048/11052/11053/11055/11058/11059/11060/11063/11067/11068

Eve Ph 1 Lot 1508