



LIVE WELL™

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 1608 1608 - 3515 Kariya
Closing Date	0000
Date	13Feb09
Contact Name(s)	Lisa Hall
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
11097	FOYER / ENTRY- WALLS-marks on left wall, see tape	✓		
11098	FOYER / ENTRY- WALLS: 1- DRYWALL cracked to left of closet above baseboard, see tape	✓		
11099	FOYER / ENTRY- DOORS-frame scratched, see tape	✓		
11102	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-filter missing in fancoil unit	X		
11104	LIVING/DINING ROOM- WINDOWS-balcony doesn't shut properly gap top right corner, see tape	✓		
11105	LIVING/DINING ROOM- WINDOWS: 1-finish piece missing to right of balcony, see tape	✓		
11108	MASTER BEDROOM- WALLS- DRYWALL rough left wall by telephone jack, see tape	✓		
11109	MASTER BEDROOM- FLOORING- CLEAN CARPET	✓		
11111	MASTER BEDROOM- CLOSET- access panel cover missing	✓		
11115	MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	✓		

11116	MAIN BATHROOM- TOILET-flange at wall not attached, see tape	✓		
11117	MAIN BATHROOM- CEILING-nailpop 3 feet from entrance, see tape	✓		
11118	MAIN BATHROOM- CEILING: 1- DRYWALL rough around exhaust fan, see tape	✓		
11121	KITCHEN- SINK-VEGETABLE SPRAYER doesn't pull freely, see tape	✓		

Date Completed:

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID#

11097/11098/11099/11102/11104/11105/11108/11109/11111/11115/11116/11117/11118/11121
Eve Ph 1 Lot 1608