AMACON

LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax:(905) 848-2827

Eve - Tower: 1 - Unit: 1708 Location

1708 - 3515 Kariya

0000 **Closing Date** 13Feb09 Date

Winston Santos Contact Name(s)

Contact Telephone#

Company: Amacon Service Carlos Bravo Attention:

Telephone:

(905) 848-2827 Fax:

Warranty Services Department - Head Office From:

Please o	Please complete the following items:						
Deficiency Number	Issue		Appointment Date/Time	Notes			
11149	FOYER / ENTRY- DOORS-door top left corner chipped -see tape	√					
11150	FOYER / ENTRY- DOORS: 1-bottom right corner chipped -see tape						
11151	FOYER / ENTRY- CLOSET-Dpanel - missing screw -see tape	/					
11154	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-fancoil missing filter -see tape b			CALL LIST CONTAIN DESMAN.			
11155	MASTER BEDROOM- WALLS-paint patchy around fire alarm signal -see tape						
11156.	MASTER BEDROOM- WALLS: 1- baseboard both sides of mirror closet doors chipped -see tape						
11157	MASTER BEDROOM- DOORS-mirror closet doors black marks on bottom of frame-see tape	<u>/</u>					
11158	MASTER BEDROOM- CLOSET- inside panel door missing -see tape						
11159	MASTER BEDROOM- ELECTRICAL/LIGHTING-outlet left wall not flush -see tape	/					
11160	MASTER BEDROOM- WINDOWS- alUMINUM casing scratched bottom						

	leftside -see tape		
11161	MAIN BATHROOM- TUB- temperature control, faucet, showerhead need silicone -see tape		
11170	KITCHEN- COUNTERTOPS-glue on countertop rightside of kitchen sink -see tape		
11172	KITCHEN- COUNTERTOPS: 1-glue on countertop left of fridge -see tape		

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905)

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 11149/11150/11151/11154/11155/11156/11157/11158/11159/11160/11161/11170/11172 Eve Ph 1 Lot 1708