

AMACON

LIVE WELL™

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827


Location	<u>Eve - Tower: 1 - Unit: 2101</u>
Closing Date	<u>2101 - 3515 Kariya</u>
Date	<u>0000</u>
Contact Name(s)	<u>19 Jan 09</u>
Contact Telephone#	<u>Wanda Golasz</u>
Company:	<u>Amacon Service</u>
Attention:	<u>Carlos Bravo</u>
Telephone:	
Fax:	<u>(905) 848-2827</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue	Appointment Date/Time	Notes	
5907	✓ FOYER / ENTRY- WALLS-right entry wall corner edge needs touch up			
5908	✓ FOYER / ENTRY- WALLS: 1-right edge of bulkhead needs touch up			
5909	✓ FOYER / ENTRY- WALLS: 2-mark on left wall 3 feet from floor			
5910	✓ FOYER / ENTRY- DOORS-scratch entry door frame by lock left side			
5914	✓ LIVING/DINING ROOM- WINDOWS-ALUMINUM frames marked/scratched			
5915	✓ LIVING/DINING ROOM- WINDOWS-ALUMINUM frames marked/scratched			
5916	✓ LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM at top left of balcony door is marked			
5917	✓ LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM at top left of balcony door is marked			
5918	✓ LIVING/DINING ROOM- WINDOWS: 2-clean threshold at balcony door			
5919	✓ LIVING/DINING ROOM- WINDOWS: 3-clean silicone left of balcony door			
5920	✓ LIVING/DINING ROOM- WALLS-wall along right window needs touch up			
5921	✓ LIVING/DINING ROOM- WALLS: 1-touch up corner by bedroom			
5922	✓ MASTER BEDROOM- WALLS-finish along window needs touch up			
5923	✓ MASTER BEDROOM- WALLS: 1-DRYWALL DENTED left wall by closet			
5924	✓ MASTER BEDROOM- DOORS-inner door to bedroom dented and chipped			
5925	✓ MASTER BEDROOM- FLOORING-gap in baseboard left wall by window			
5926	✓ MASTER BEDROOM- ELECTRICAL/LIGHTING-electrical panel scratched			
5927	✓ MASTER BEDROOM- WINDOWS-top right ALUMINUM frame marked			
5931	✓ MAIN BATHROOM- DOORS: 1-touch up marks front of bathroom door exterior			
5932	✓ MAIN BATHROOM- DOORS: 2-nails popped along interior frame			
5933	✓ MAIN BATHROOM- TUB-clean up silicone rear edge of tub			
5935	✓ MAIN BATHROOM- FLOORING-silicone at bottom of inner door frame			
5938	✓ MAIN BATHROOM- ELECTRICAL/LIGHTING-realign cover plate			
5939	✓ KITCHEN- CABINETS-CORNER CABINET needs cleaning at top			
5947	✓ KITCHEN- COUNTERTOPS-clean glue/silicone under outlet by drawers			
5948	✓ KITCHEN- SINK-right sink scuffed			
5950	✓ KITCHEN- APPLIANCE-scuff marks on fridge			
5951	✓ KITCHEN- APPLIANCE: 1-scratch on dishwasher door			
5954	✓ KITCHEN- CEILING: 1-crack directly above island			
5955	✓ KITCHEN- WALLS-bulkhead for microwave exhaust not finished			
5956	✓ KITCHEN- WALLS: 1-left of telephone plug discoloration			
5957	✓ KITCHEN- WALLS: 2-touch up by nook corner			
5958	✓ LAUNDRY CLOSET- DOORS-scratches interior or door			
5963	✓ KITCHEN- CABINETS: 1-centre cabinet under sink has holes inside			
5967	✓ MAIN BATHROOM- VANITY CABINETS-chip inside left door			
5969	✓ KITCHEN- CABINETS: 6-gap at bottom of gable and rough finish along bottom			

Date Completed:

Jan 20/09 1/8

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#
5907/5908/5909/5910/5914/5915/5916/5917/5918/5919/5920/5921/5922/5923/5924/5925/5926/5927/5931/5932/5933/5935/5938/5939/5947/5948/5950/5951/5954/5955/5956/5957/5958/5963/5967/5969
Eve Ph 1 Lot 2101