

A M A C O N

L I V E W E L L

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 2103</u>
	<u>2103 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>19Jan09</u>
Contact Name(s)	<u>Wenbin Li</u>
Contact Telephone#	
Company:	<u>Amacon Service</u>
Attention:	<u>Carlos Bravo</u>
Telephone:	
Fax:	<u>(905) 848-2827</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:

Deficiency Number	Issue		Appointment Date/Time	Notes
6417 ✓	FOYER / ENTRY- DOORS-rightside of entry doorframe paint chipped by lock		✓	
6418 ✓	FOYER / ENTRY- CLOSET-access panel to be attached to wall		✓	
6419 ✓	LIVING/DINING ROOM- WALLS-pencil marks left wall 2' from kitchen island		✓	
6421 ✓	KITCHEN- CABINETS-upper cabinets right of fridge -- doors to be adjusted		✓	
6423 ✓	KITCHEN- CABINETS: 1-3rd cabinet right of fridge doors to be adjusted		✓	
6428 ✓	KITCHEN- CABINETS: 3-cabinets under sink need doors to be adjusted		✓	
6430 ✓	KITCHEN- CABINETS: 4-large lower cabinet left of fridge to be doors to be adjusted - also add shelves		✓	
6432 ✓	KITCHEN- CABINETS: 5-upper cabinet doors to be adjusted - leftside of microwave		✓	
6433 ✓	KITCHEN- CABINETS: 6-cabinet above microwave doors to be adjusted		✓	
6435 ✓	KITCHEN- WALLS-bulkhead above microwave drywall needs to sanded and painted		✓	