

**AMACON**

LIVE WELL®

**Warranty Services****Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 2106</u>
<b>Closing Date</b>	<u>2106 - 3515 Kariya</u>
<b>Date</b>	<u>0000</u>
<b>Contact Name(s)</b>	<u>19Jan09</u>
<b>Contact Telephone#</b>	<u>Joan Hing King</u>
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
6542	GUEST BEDROOM 1- FLOORING: 1-left wall - carpet lifting around wall edges		✓	
6543	MASTER BEDROOM- ELECTRICAL/LIGHTING-telephone jack - left wall plate missing - see tape		✓	
6546	MAIN BATHROOM- VANITY CABINETS-drawer under vanity cabinet doors -- cannot open -- look for tape		✓	
6551	KITCHEN- CABINETS-lower large cabinet leftside of stove - door needs to be adjusted - see tape		✓	
6552	KITCHEN- CABINETS: 1-upper cabinets right of fridge - doors to be adjusted -- see tape		✓	
6554	KITCHEN- CABINETS: 2-upper cabinet rightside of microwave - bottom hinge not attached		✓	
6605	KITCHEN- WALLS-bulkhead above microwave - drywall needs to be sanded and painted -- see tape		✓	

Date Completed:

Amacon Customer Care Signature: