

AMACON

LIVE WELL

**Warranty Services
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2107
Closing Date	2107 - 3515 Kariya
Date	0000
Contact Name(s)	19Jan09
Contact Telephone#	Angela He
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:			
Deficiency Number	Issue	Appointment Date/Time	Notes
6606	BOYER / ENTRY- WALLS-DENTED	✓	
6607	BOYER / ENTRY- WALLS-DRYWALL MARKED BULKHEAD LEFTOF DOOR IN LINE WITH TAPE	✓	
6608	BOYER / ENTRY- DOORS-FRAME PAINT TOUCH UP NEEDED LEFTOF LOCK & TO FLOOR	✓	
6610	LIVING/DINING ROOM- FLOORING: 1-TSTRIP LEFTOF ENNTRANCE TO KITCHEN GAP AGAINST WALL	✓	
6611	LIVING/DINING ROOM- WINDOWS-ALUMINUM SCRATCHED RIGHTOF SLIDER BOTTOM PANE	✓	
6614	LIVING/DINING ROOM- WALLS-REPAINT LEFTOF LAUNDRY CLOSET AND WALL ACROSS SEETAPE	✓	
6615	LIVING/DINING ROOM- WALLS: 1-REPAINT RIGHTOF LAUNDRY CLOSET CORNER SEETAPE	✓	
6616	LIVING/DINING ROOM- WALLS: 2- TOUCH UP WHERE MARKED LEFTOF GUEST BEDROOM #1 DOOR @ LIGHT SWITCH.	✓	
6617	LIVING/DINING ROOM- WALLS: 3-DIRTY RIGHTOF WINDOWS LEFTOF ENTRY TO KITCHEN	✓	
6618	GUEST BEDROOM 1- WALLS-REPAINT TOUCH UP CORNER RIGHTOF WINDOWS	✓	cleaning
6619	GUEST BEDROOM 1- WALLS: 1-DRYWALL REPAIR WHERE NOTED PATCH/PAINT RIGHTOF WINDOWS TOP OF SOCKET	✓	
6620	GUEST BEDROOM 1- WALLS: 2-REPAINT LEFTOF WINDOWS BASEBOARD A D 2INCHES UP FROM FLOR	✓	
6621	GUEST BEDROOM 1- WALLS: 3-DRYWALL REPAIR WHERE NOTED PATCH/PAINT HOLE BOTTOM LEFTOF HEATVENT	✓	
6622	GUEST BEDROOM 1- WALLS: 4-BASEBOARD BELOW CABLE BOX REPAINT AND SEETAPE TOWARDS WINDOWS SPOTS	✓	
6626	MASTER BEDROOM- WALLS-DRYWALL REPAIR WHERE NOTED PATCH/PAINT AROUND FIRE ALARM PLATE	✓	
6627	MASTER BEDROOM- WALLS: 1-RIGHTOF THERMOSTAT DRYWALL REPAIR WHERE NOTED PATCH/PAINT	✓	
6628	MASTER BEDROOM- WALLS: 2-DRYWALL REPAIR WIERE NOTED PATCH/PAINT BULKHEAD ABOVE TAPE & CABLE PLUG	✓	
6629	MASTER BEDROOM- WALLS: 3-REPAINT BESIDE FANCOIL RIGHT SIDE STREAKY	✓	
6630	MASTER BEDROOM- WALLS: 4-DRYWALL REPAIR AROUND BREAKER PANEL	✓	
6639	MASTER BEDROOM- CEILING: 4-CLEAN EXCESSIVE STIPPLE INFRONT OF WINDOWS IN CORNER @ BULKHEAD	✓	
6640	MASTER BEDROOM- CLOSET-DRYWALL 2HOLES IN CLOSET TO RIGHTOF ENSUITE	✓	
6641	MASTER BEDROOM- CLOSET: 1-DRYWALL TOUCH UP IN CLOSET LEFTOF ENSUITE WHEN FACING ENSUITE SEETAPE	✓	
6642	MASTER BEDROOM- ELECTRICAL/LIGHTING-COVER PLATE CROOKED FIRE ALARM	✓	
6643	MASTER BEDROOM- WINDOWS-EXCESSIVE GAP @STRIP & CEILING TOPRIGHT CORNER OF EAST WINDOW AND IN MIDDLE	✓	
6644	MAIN BATHROOM- WALLS-AROUND LIGHT SWITCH REPAINT	✓	
6645	MAIN BATHROOM- WALLS: 1-REPAINT BELOW TOWEL ROD SEETAPE	✓	
6646	MAIN BATHROOM- DOORS-TOUCH UP FRONT OF DOOR SEETAPE	✓	
6647	MAIN BATHROOM- TUB-SILICONE GAPS ALONG FLOOR & TUB	✓	
6653	ENSUITE BATHROOM- DOORS-PAINT TOUCH UP ON DOOR TOP BETWEEN FACES SEETAPE	✓	
6657	KITCHEN- CABINETS-NEXT TO MICROWAVE LEFTOF SHELF NOT INSTALLED	✓	
6658	KITCHEN- CABINETS: 1-UNDER SINK CHIPPED SEETAPE PAINT TOUCH UP	✓	
6661	KITCHEN- ELECTRICAL/LIGHTING: 1-STRAIGHTEN OUTLET RIGHTOF RANGE	✓	Kitchen
6662	KITCHEN- ELECTRICAL/LIGHTING: 2-DOUBLE SWITCH PLATE STRAIGHTENING LEFTOF FIXED WINDOWS	✓	
6663	KITCHEN- CEILING-PATCH/REPAINT AT EXHAUST FAN ABOVE MICRWA VE	✓	
6664	KITCHEN- WINDOWS-STRIP ABOVE SINK TOP GAPS FROM WALL	✓	
6665	KITCHEN- WINDOWS: 1-CAULKING CLEAN UP AT LARGE FIXED WINDOWS AT BOTTOM	✓	

6667	KITCHEN- WALLS-DRYWALL TOUCH UP AT ENTRY RIGHT OF FRIDGE		<input checked="" type="checkbox"/>
6668	KITCHEN- WALLS: 1-DRYWALL REPAIR WHERE NOTED PATCH/PAINT SEETAPE LEFT OF MICROWAVE		<input checked="" type="checkbox"/>
7278	MAIN BATHROOM- VANITY CABINETS-BELOW TOILET PAPER HOLDER CABINET AND FLOOR TILES NOT ALIGNED		<input checked="" type="checkbox"/> <i>Mark Fritz</i>

Date Completed:

Jan 22/09/18

Amacon Customer Care Signature:

Mark Fritz

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -**Forms****Menu****ID#**

6606/6607/6608/6610/6611/6614/6615/6616/6617/6618/6619/6620/6621/6622/6626/6627/6628/6629/6630/6639/6640/6641/6642/6643/6644/6645/6646/6647/6653/6657/6658/6661/6662/6663/6664/66

Eve Ph 1 Lot 2107