



LIVE WELL

Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 210 210 - 3515 Kariya
Closing Date	0000
Date	11Feb09
Contact Name(s)	Adwoa Adu-Gyamfi and Elvin Frempong-Manso
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
10527	FOYER / ENTRY- CLOSET-door not sliding properly	X		J-J Need New Door
10533	LIVING/DINING ROOM- WINDOWS: 2-ALUMINUM frame dented and scratched, see tape	X		ALLAN Windows
10534	LIVING/DINING ROOM- WINDOWS: 3-mark right side of balcony door, see tape	✓		
10535	LIVING/DINING ROOM- WINDOWS: 4-caULKING at bottom of balcony door rough and messy, see tape	✓		
10536	LIVING/DINING ROOM- WALLS-J-mold craked/gaps at balcony door, see tape	✓		
10537	LIVING/DINING ROOM- WALLS: 1- DRYWALL DENTED below outlet, right wall, see tape	✓		
10538	LIVING/DINING ROOM- WALLS: 2- quarter round chipped , right wall, see tape	✓		
10539	MASTER BEDROOM- WALLS- DRYWALL DENTED below thermostat, see tape	✓		
10540	MASTER BEDROOM- DOORS-door stopper missing, see tape	✓		

10541 ✓	MASTER BEDROOM- FLOORING- chip in baseboard left wall in front of window, see tape	✓		
10543 ✓	MASTER BEDROOM- WINDOWS: 1-CAULKING required along bottom, see tape	✓		
10545 ✓	MAIN BATHROOM- WALLS-tile cracked at showerhead, see tape	✓		
10546 ✓	MAIN BATHROOM- TUB-silicone around showerhead , tap and faucet, see tape	✓		
10548 ✓	MAIN BATHROOM- SINK-sink doesn't hold water	✓		

Date Completed:

FEB 12, 09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

[Back - Forms Menu](#)

ID#

10527/10533/10534/10535/10536/10537/10538/10539/10540/10541/10543/10545/10546/10548

Eve Ph 1 Lot 210