

**AMACON****LIVE WELL****Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<u>Eve - Tower: 1 - Unit: 2110</u> <u>2110 - 3515 Kariya</u>
<b>Closing Date</b>	<u>0000</u>
<b>Date</b>	<u>19Jan09</u>
<b>Contact Name(s)</b>	<u>Margarita Lontoc</u>
<b>Contact Telephone#</b>	
<b>Company:</b>	<u>Amacon Service</u>
<b>Attention:</b>	<u>Carlos Bravo</u>
<b>Telephone:</b>	
<b>Fax:</b>	<u>(905) 848-2827</u>
<b>From:</b>	<u>Warranty Services Department - Head Office</u>


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
6696	✓ FOYER / ENTRY- DOORS-frame right side of entry door scratched		✓	
6697	✓ LIVING/DINING ROOM- WINDOWS-caulking on aluminum top left corner balcony door		✓	
6698	✓ LIVING/DINING ROOM- WINDOWS: 1-scratch on aluminum frame to left of balcony door 4 feet from floor		✓	
6700	✓ LIVING/DINING ROOM- WALLS- right wall drywall rough/dented where marked		✓	
6701	✓ LIVING/DINING ROOM- WALLS: 1- DRYWALL DENTED left of window 4 feet from floor		✓	
6702	✓ MASTER BEDROOM- WALLS- DRYWALL chipped left wall 4 feet from closet		✓	
6703	✓ MASTER BEDROOM- WALLS: 1- DRYWALL DENTED below outlet by telephone jack		✓	
6704	✓ MASTER BEDROOM- WALLS: 2- paint overbrushed along left window edge		✓	
6705	✓ MASTER BEDROOM- FLOORING- excessive gap to left of closet		✓	

6706	✓ MASTER BEDROOM- FLOORING: 1-mark on carpet left of closet		✓	
6707	✓ MASTER BEDROOM- FLOORING: 2-marks on baseboard below outlet by telephone jack		✓	
6708	✓ MASTER BEDROOM- WINDOWS- remove caulking from ALUMINUM frame right side		✓	
6709	✓ MASTER BEDROOM- WINDOWS: 1-caulking needed along top of windows		✓	OK
6710	✓ MAIN BATHROOM- WALLS- DRYWALL DENTED at towel rack		✓	
6711	✓ MAIN BATHROOM- DOORS-mark on exterior of door above handle		✓	
6712	✓ MAIN BATHROOM- DOORS: 1-chip interior door frame 5 feet from floor		✓	
6713	✓ MAIN BATHROOM- ELECTRICAL/LIGHTING-straighten light switch cover		✓	
6717	KITCHEN- WALLS-DRYWALL discoloration right wall at island		✓	
6718	LAUNDRY CLOSET- NOTE-dryer door loose and dryer sits crooked		✓	
7279	KITCHEN- CABINETS-realign upper cabinets			Kitchener's

Date Completed:

Jan 22/09/18

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

**Back -**  
**Forms**  
**Menu**

ID#

6696/6697/6698/6700/6701/6702/6703/6704/6705/6706/6707/6708/6709/6710/6711/6712/6713/6717/6718/7279

Eve Ph 1 Lot 2110