AMACON

Warranty Services Work Order

WELL LIVE

Phone: (905) 848-2069 Fax:(905) 848-2827

Eve - Tower: 1 - Unit: 2210 Location 2210 - 3515 Kariya **Closing Date** 0000

27Jan09 Date Stephane Vallin

Contact Name(s) Contact Telephone#

Company:

From:

Amacon Service Carlos Bravo Attention: Telephone:

(905) 848-2827 Fax:

Warranty Services Department - Head Office

Please complete the following items:							
Deficiency Number	Issue		Appointment	Notes			
	/		Date/Time				
/	FOYER / ENTRY- DOORS-both sides						
	of entry doorframe pint touchups - see tape						
3077	MASTER BEDROOM- WALLS-steup						
8077	up to large window - J mould caulking						
	to be sanded		V				
8078	MASTER BEDROOM- WALLS: 1-		7				
	baseboard seam right wall - 2 feet from						
	walk-in entry - needs to be sanded - see tape						
8079	MASTER BEDROOM- WALLS: 2-		6/				
	høle in baseboard 3 feet right of cable		1. /				
	outlet - see tape						
8080	MASTER BEDROOM- DOORS-	li.	./				
	bedroom doorknowb loose	<u> </u>					
8081	MASTER BEDROOM- DOORS: 1-	 		<u> </u>			
	entry door to bedroom inside of door dented - see tape	<u> </u>					
0002	MASTER BEDROOM- CLOSET-		1				
8083	baseboard upon entering closet - center	<u> </u>					
	chipped see tape						
8084	MASTER BEDROOM- CLOSET: 1-		//				
	left center wall above baseboard - needs						
	sanding	<u> </u>	14				
8085	MASTER BEDROOM- CLOSET: 2-						
	left wall below closet shelves wall	11					

			/
	dented - see tape		
	MASTER BEDROOM- CLOSET: 3- right wall - 6 inches above baseboard - black mark		
	MAIN BATHROOM- WALLS-corner bead below towel rack - lifting by tile - see tape		
8088	MAIN BATHROOM- WALLS: 1- towel rack - right side loose	1/	
8089 /	MAIN BATHROOM- TUB-shower bead needs to be sealed to tiles	رن	
8090 /	MAIN BATHROOM- TUB: 1-bath faucet loose - when turning on or off		
8091	MAIN BATHROOM- TUB: 2-tub wall - above tub - left edge scratched tiles - see tape		mega
8093	MAIN BATHROOM- VANITY CABINETS-access panel inside vanity needs to be sealed	OK	
8094	MAIN BATHROOM- FLOORING- paint on floor beside toilet		
8095	KITCHEN- CABINETS-lazy susan shelves not in		Kitchens
8099	KITCHEN- APPLIANCE-micriwave not working		
8100	KITCHEN- BACKSPLASH-no grout between tiles - needs grout		mega

ustorner/Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905)

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -

Forms Menu

ID#

Eve Ph 1 Lot 2210