



UPDATER

Warranty Services
Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2303
Closing Date	2303 - 3515 Kariya
Date	0000
Contact Name(s)	27Jan09
Contact Telephone#	Carey Gata and Antonio Gata
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:

Deficiency Number	Issue	Appointment Date/Time	Notes
8126	FOYER / ENTRY- WALLS-dent by mirror closet door - see tape	✓	
8127	FOYER / ENTRY- WALLS: 1-crack in wall - left side above doorframe - see tape	✓	
8128	FOYER / ENTRY- WALLS: 2-dents in wall right of closet - see tape	✓	
8129	FOYER / ENTRY- DOORS-front doorframe chipped by handle	✓	
8132	LIVING/DINING ROOM- WINDOWS-scratched above window frame	✓	
8133	LIVING/DINING ROOM- WALLS-dents - wall right of balcony door see tape - several dents	✓	
8134	LIVING/DINING ROOM- WALLS: 1-doorframe chipped several place - see tape	✓	
8135	LIVING/DINING ROOM- WALLS: 2-dented left edge 6 in from floor - by window - see tape	✓	
8136	LIVING/DINING ROOM- WALLS: 3-dents left edge by window - see tape	✓	
8137	LIVING/DINING ROOM- WALLS: 4-paint not matching - several spots see tape	✓	
8138	MASTER BEDROOM- WALLS-dent left wall 3 in from ceiling see tape	✓	
8139	MASTER BEDROOM- WALLS: 1-centre wall several paint touchups needed - see tape	✓	
8140	MASTER BEDROOM- WALLS: 2-edges dent right side of window - see tape	✓	
8141	MASTER BEDROOM- WALLS: 3-JMOULD paint needs to be cleaned up - right upper edge -- see tape	✓	
8142	MASTER BEDROOM- WALLS: 4-nail pop below window ledge - see tape	✓	
8143	MASTER BEDROOM- WALLS: 5-left side j mould needs to be cleaned - paint to be removed - see tape	✓	
8144	MASTER BEDROOM- FLOORING-carpet stained - several brown spots see tape	✓	
8146	MAIN BATHROOM- WALLS-left wall by vanity cabinet dent - see tape	✓	
8147	MAIN BATHROOM- WALLS: 1-right side by light dented - see tape	✓	
8148	MAIN BATHROOM- WALLS: 2-tile - right edge black marks - see tape	✓	
8149	MAIN BATHROOM- TUB-chipped in tub - see tape	✓	
8150	MAIN BATHROOM- TUB: 1-tub plug not sealing - water not staying in tub	✓	
8151	MAIN BATHROOM- COUNTERTOPS-bracket below cabinet not stable	✓	
8152	MAIN BATHROOM- VANITY CABINETS-right cabinet door needs adjusting	✓	
8154	KITCHEN- CABINETS-cabinets below sink need to be adjusted - see tape	✓	
8155	KITCHEN- CABINETS: 1-upper cabinet door edge touching microwave - see tape	✓	
8159	KITCHEN- COUNTERTOPS-left side of sink -- glue marks	✓	
8160	KITCHEN- ELECTRICAL/LIGHTING-1 of the bulbs on track lighting not working	✓	
8161	KITCHEN- ELECTRICAL/LIGHTING: 1-GFI - outlet needs to be pushed in - see tape	✓	
8162	KITCHEN- WALLS-dented right side by telephone jack - see tape	✓	
8163	KITCHEN- WALLS: 1-dented right edge by telephone jack see tape	✓	
8164	KITCHEN- WALLS: 2-wall above microwave cabinets right edge dented - see tape	✓	
8165	KITCHEN- WALLS: 3-wall above microwave cabinets left edge dented nail marks - see tape	✓	

Date Completed:

JANUARY 28, 09

Amacon Customer Care Signature:

[Signature]

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 8126/8127/8128/8129/8132/8133/8134/8135/8136/8137/8138/8139/8140/8141/8142/8143/8144/8146/8147/8148/8149/8150/8151/8152/8154/8155/8159/8160/8161/8162/8163/8164/8165
Eve Ph 1 Lot 2303