



Warranty Services Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 2505
Closing Date	2505 - 3515 Kariya
Date	0000
Contact Name(s)	28Jan09
Contact Telephone#	Yeung Sing Lo and Dip Mui Sit
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office


Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
9374	FOYER / ENTRY- WALLS-DRYWALL DENTED right wall by entry where taped	- Group Assign		
9375	FOYER / ENTRY- WALLS: 1-marks on right wall where taped	- Group Assign		
9376	FOYER / ENTRY- FLOORING-mark on baseboard right wall 2 feet from closet where taped	- Group Assign		
9377	FOYER / ENTRY- FLOORING: 1-mark on baseboard right wall 2 feet from laundry closet where taped	- Group Assign		
9378	FOYER / ENTRY- CEILING-AIR HOLES by bulkhead above closet	- Group Assign		
9379	FOYER / ENTRY- CLOSET-access panel cover is not flush	- Group Assign		
9380	LIVING/DINING ROOM- CEILING-crack top corner to left of guest bedroom	- Group Assign		
9381	LIVING/DINING ROOM- WALLS-marks on right wall, above telephone jack, where taped	- Group Assign		
9382	LIVING/DINING ROOM- WALLS: 1-DRYWALL DENTED left of fan coil unit where taped	- Group Assign		
9383	LIVING/DINING ROOM- WALLS: 2-mark 4 feet from master bedroom entry left wall, where taped	- Group Assign		
9384	GUEST BEDROOM 1- CEILING-AIR HOLES at top right of window	- Group Assign		
9385	GUEST BEDROOM 1- CLOSET-air holes around edge of closet ceiling	- Group Assign		
9386	GUEST BEDROOM 1- WINDOWS-inside window doesn't slide	- Group Assign		
9387	GUEST BEDROOM 1- WINDOWS: 1-ALUMINUM TRIM crooked	- Group Assign		
9388	MASTER BEDROOM- WALLS-crack in bulkhead to right of closet, left wall	- Group Assign		
9389	MASTER BEDROOM- WALLS: 1-mark on drywall to left of window where taped	- Group Assign		
9390	MASTER BEDROOM- WALLS: 2-mark on drywall below fire silencer where taped	- Group Assign		
9391	MASTER BEDROOM- FLOORING-CLEAN CARPET	- Group Assign		
9392	MASTER BEDROOM- CEILING-crack right side 3 feet from fan coil unit	- Group Assign		
9393	MASTER BEDROOM- ELECTRICAL/LIGHTING-light between closets not working	- Group Assign		
9394	MASTER BEDROOM- WINDOWS-ALUMINUM frame inside window is crooked, upper right	- Group Assign		
9395	MASTER BEDROOM- WINDOWS: 1-marks on ALUMINUM Frame where taped	- Group Assign		
9396	MAIN BATHROOM- TUB-stopper missing	- Group Assign		
9397	ENSUITE BATHROOM- WALLS-grout needed lower tile in front of tub where taped	- Group Assign		
9398	ENSUITE BATHROOM- DOORS-top of door crack and delaminating	- Group Assign		
9399	ENSUITE BATHROOM- TUB-stopper missing	- Group Assign		
9400	KITCHEN- CABINETS-puncture hole upper cabinet to right of fridge, lower shelf	- Group Assign		
9401	KITCHEN- SINK-stoppers missing	- Group Assign		

9402	KITCHEN- ELECTRICAL/LIGHTING-no power at outlets to right of stove and right of sink	- Group Assign	✓	
9403	KITCHEN- ELECTRICAL/LIGHTING: 1-under cabinet lighting missing cabinets flanking sink where taped	- Group Assign		ELECTRIC.
9404	KITCHEN- WINDOWS-ALUMINUM frame marked where taped	- Group Assign	✓	
9405	KITCHEN- BACKSPLASH-tile marked to right of sink 2nd from top	- Group Assign	✓	
9406	KITCHEN- WALLS-drywall wall rough corner to right of microwave where taped	- Group Assign	✓	
9407	KITCHEN- WALLS: 1-mark to left of balcony door where taped	- Group Assign	✓	

Date Completed:

January 29, 09 8

Amacon Customer Care Signature



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#

9374/9375/9376/9377/9378/9379/9380/9381/9382/9383/9384/9385/9386/9387/9388/9389/9390/9391/9392/9393/9394/9395/9396/9397/9398/9399/9400/9401/9402/9403/9404/9405/9406/9407
Eve Ph 1 Lot 2505