AMACON

Warranty Services Work Order

LIVE WELL

Phone: (905) 848-2069 Fax:(905) 848-2827

Location Eve - Tower: 1 - Unit: 2608

2608 - 3515 Kariya

Closing Date

0000

Date

27Mar09

Contact Name(s)

Grace Chan in Trust for

Contact Telephone#

Company:

Amacon Service

Attention:

Carlos Bravo

Telephone:

(905) 848-2827

Fax: From:

Warranty Services Department - Head Office

Please complete the following items:						
Deficiency Number	Issue		Appointment	Notes		
			Date/Time			
14133	FOYER / ENTRY- WALLS-left wall on entering below security rough in black marks - see tape					
14134	FOYER / ENTRY- WALLS: 1-right wall black marks - see tape					
14135	EOYER ENTRY-FLOORING-tiles in entry paint on them- see tape					
14136	FOYER / ENTRY- CLOSET-paint on tiles			,		
14137	FOYER / ENTRY- CLOSET: 1-mirror closet doors need to aligned - see tape					
14147	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-light switch has paint on it - see tape					
14149	LIVING/DINING ROOM- WINDOWS-balcony doorframe not finished - see tape					
14151	LIVING/DINING ROOM- WINDOWS: 1-large gap in window frame - leftside by balcony doorframe - see tape					
14153	MASTER BEDROOM- WALLS- baseboard chipped leftside of mirror closet doors - see tape					
14154	MASTER BEDROOM- DOORS-mirror					

	closet doors chipped bottom - see tape		
14156	MAIN BATHROOM- TUB-tub facing cracked - see tape		Lini
14158	MAIN BATHROOM- FLOORING- paint on floor below towel rack - see tape		
14163	LAUNDRY CLOSET- WALLS- AROUND		

Date Completed: 109

Amacon Austomer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 14133/14134/14135/14136/14137/14147/14149/14151/14153/14154/14156/14158/14163 Eve Ph 1 Lot 2608