## AMACON

## **Warranty Services** Work Order

LIVE WELL

Phone: (905) 848-2069 Fax:(905) 848-2827

Location	Eve Toward Hait 2010			
Lucanun	<b>Eve - Tower: 1 - Unit: 2810</b>			
	<u> 2810 - 3515 Kariya</u>			
Closing Date	0000			
Date	<u>05Feb09</u>			
Contact Name(s)	Marilen Patricio and Abraham Patricio			
Contact Telephone#	·			
Company:	Amacon Service			
Attention:	Carlos Bravo			
Telephone:				
Fax:	(905) 848-2827			
From:	Warranty Services Department - Head Office			

Please complete the following items:							
Deficiency Number	Issue		Appointment Date/Time		Notes		
8882	LIVING/DINING ROOM- WALLS- paint patchy, see tape	-		Con	PAINTER		
8883	LIVING/DINING ROOM- WALLS: 1-drywall marked to right of balcony dor, see tape						
8884	LIVING/DINING ROOM- WALLS: 2- excessive gap baseboard, left wall, see tape						
II /	MASTER BEDROOM- WALLS-mark on drywall, see tape						
8886	MASTER BEDROOM- WALLS: 1- mark on baseboard, see tape	V					
8887	MASTER BEDROOM- WALLS: 2- onip in baseboard, right wall, see tape						
	MASTER BEDROOM- WALLS: 3- excessive gap in basebord						
8890 <b>V</b>	MASTER BEDROOM- WINDOWS- excessive silicone on alumi um frame, see tape						
8891	MASTER BEDROOM- WINDOWS: 1-ALUMINUM frame buckled, bottom right corner, middle window, see tape	$\checkmark$					

Date Completed:

macon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back - Forms Menu

ID# 8882/8883/8884/8885/8886/8887/8888/8890/8891 Eve Ph 1 Lot 2810

