

AMACON

LIVE WELL

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	<u>Eve - Tower: 1 - Unit: 2901</u> <u>2901 - 3515 Kariya</u>
Closing Date	<u>0000</u>
Date	<u>09Feb09</u>
Contact Name(s)	<u>Jose Roy Torres</u>
Contact Telephone#	
Company:	<u>Amacon Service</u>
Attention:	<u>Carlos Bravo</u>
Telephone:	
Fax:	<u>(905) 848-2827</u>
From:	<u>Warranty Services Department - Head Office</u>

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
8927	FOYER / ENTRY- DOORS-mark on top of frame, centre of frame		✓	
8928	LIVING/DINING ROOM- WINDOWS- marks/scratches on balcony door and surrounding aluminum frame, see tape		✓	
8929	LIVING/DINING ROOM- WINDOWS: 1-scratch/mark left window, see tape		✓	
8930	LIVING/DINING ROOM- WINDOWS: 2-j-mold not flush, left window, see tape		✓	
8931	LIVING/DINING ROOM- WINDOWS: 3-excess silicone, left window, see tape		✓	
8932	LIVING/DINING ROOM- WALLS-paint patchy, left wall, see tape		—	Paint all wall
8933	LIVING/DINING ROOM- WALLS: 1-seams showing, right wall, see tape		—	Patched Paint Wall
8934	LIVING/DINING ROOM- WALLS: 2-baseboard not joined properly, see tape		✓	
8935	LIVING/DINING ROOM- WALLS: 3-marks and cracks between telephone jack and electrical outlet, see tape		—	Patched Paint Wall
8936	LIVING/DINING ROOM- WALLS: 4-discoloration, marks, holes right wall		✓	
8937	MASTER BEDROOM- WALLS-air vent not flush, see tape		✓	
8938	MASTER BEDROOM- DOORS-door not latching properly		✓	
8939	MASTER BEDROOM- WINDOWS-remove excess silicone, see tape		✓	
8941	MASTER BEDROOM- WINDOWS: 2-marks on ALUMINUM frame, see tape		✓	

8942	MASTER BEDROOM- WINDOWS: 3-window sill cracked, see tape TOUCH-UP WHERE		✓	
8943	MAIN BATHROOM- DOORS-door does not unlock using interior door handle		✓	
8945	MAIN BATHROOM- VANITY CABINETS-marks on cabinet door, see tape		✓	
8946	KITCHEN- CABINETS-mark cabinet to right of microwave, see tape		✓	
8947	KITCHEN- CABINETS: 1-gable delaminating to left of dishwasher, see tape		—	Kitchen's
8948	KITCHEN- CABINETS: 2-marks underside of upper cabinet to right of microwave, see tape		✓	
8949	KITCHEN- COUNTERTOPS-excessive gap underside island countertop facing living room, see tape		—	Kitchen's
8952	KITCHEN- APPLIANCE-marks/scratch front of fridge door, see tape		✓	
8953	LAUNDRY CLOSET- DOORS-door doesn't latch properly		✓	

Date Completed:

Feb 09/09/18

Amacon Customer Care Signature:

Marsby

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

**Back -
Forms
Menu**

ID#

8927/8928/8929/8930/8931/8932/8933/8934/8935/8936/8937/8938/8939/8941/8942/8943/8945/8946/8947/8948/8949/8952/8953
Eve Ph 1 Lot 2901