

**A M A C O N**

L I V E   W E L L ®

**Warranty Services****Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<b>Eve - Tower: 1 - Unit: 3003</b> <b>3003 - 3515 Kariya</b>
<b>Closing Date</b>	<b>0000</b>
<b>Date</b>	<b>10Feb09</b>
<b>Contact Name(s)</b>	<b>Shui Lin Cheung</b>
<b>Contact Telephone#</b>	
<b>Company:</b>	<b>Amacon Service</b>
<b>Attention:</b>	<b>Carlos Bravo</b>
<b>Telephone:</b>	
<b>Fax:</b>	<b>(905) 848-2827</b>
<b>From:</b>	<b>Warranty Services Department - Head Office</b>

**Please complete the following items:**


Deficiency Number	Issue		Appointment Date/Time	Notes
9825	✓ FOYER / ENTRY- DOORS-doorframe has chipped - see tape	✓		
9826	✓ FOYER / ENTRY- DOORS: 1-doorframe top chipped - see tape	✓		
9828	✓ FOYER / ENTRY- CLOSET-black marks on mirror doors - see tape	✓		
9830	✓ LIVING/DINING ROOM- WINDOWS-balcony doorframe scratched - see tape	✓		
9831	✓ LIVING/DINING ROOM- WINDOWS: 1-caulking around balcony - has black marks -see tape	✓		
9832	✓ LIVING/DINING ROOM- WINDOWS: 2-alUMINUM sill both corners black marks - see tape	✓		
9833	✓ LIVING/DINING ROOM- WINDOWS: 3-alUMINUM casing/rightside scratched - see tape	✓		
9834	✓ LIVING/DINING ROOM- WALLS-baseboard left wall - seams showing and chipped see tape	✓		
9835	✓ LIVING/DINING ROOM- WALLS: 1-far left corner baseboard chipped -see tape	✓		
9836	✓ LIVING/DINING ROOM- WALLS: 2-left corner edge by window chipped - see tape	✓		
9837	✓ MASTER BEDROOM- WALLS-wall surrounding mirror closet doors chipped - see tape	✓		
9838	✓ MASTER BEDROOM- WALLS: 1-small left wall - touchups needed	✓ →		PAINTER ✓
9839	✓ MASTER BEDROOM- WALLS: 2-left wall scratched -see tape	✓ →		PAINTER ✓
9840	✓ MASTER BEDROOM- FLOORING-carpet stained	✓		
9841	✓ MASTER BEDROOM- FLOORING: 1-carpet inside closet - long cut by wall			
9843	✓ MASTER BEDROOM- ELECTRICAL/LIGHTING-cable outlet not flush -- drywall showing rightside - see tape	✓		
9844	✓ MASTER BEDROOM- WINDOWS-caulking on window sill needs to be cleaned up -- screw heads showing thru- see tape ,	✓		

9845	✓	MAIN BATHROOM- DOORS-outside doorframe bumps - leftside	✓		
9846	✓	MAIN BATHROOM- DOORS: 1-rightside of the outside doorframe chipped see tape	✓		
9847	✓	MAIN BATHROOM- TUB-caulking around tub -- needs to fixed - see tape	✓		
9848	✓	MAIN BATHROOM- TOILET-toilet seat not flush -- crooked - see tape	✓		
9849	✓	MAIN BATHROOM- CEILING-ceiling rough by fan - see tape	✓		
9863	✓	KITCHEN- BACKSPLASH-above outlet left of stove -- need caulking -see tape	✓		
9864	✓	KITCHEN- WALLS-wall kitchen by gable corner strip chipped - see tape	✓		
9865	✓	KITCHEN- WALLS: 1-bulkhead above microwave needs paint touchups - see tape	✓		

Date Completed:

FEBRUARY 10, 09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.  
**Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Back -**  
**Forms**  
**Menu**

ID#

9825/9826/9828/9830/9831/9832/9833/9834/9835/9836/9837/9838/9839/9840/9841/9843/9844/9845/9846/9847/9848/9849/9863/9864/9865  
 Eve Ph 1 Lot 3003