

LIVE WELL

Warranty Services

Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

| | |
|---------------------------|---|
| Location | <u>Eve - Tower: 1 - Unit: 3010</u> |
| | <u>3010 - 3515 Kariya</u> |
| Closing Date | <u>0000</u> |
| Date | <u>10Feb09</u> |
| Contact Name(s) | <u>Khalil Younan</u> |
| Contact Telephone# | |
| Company: | <u>Amacon Service</u> |
| Attention: | <u>Carlos Bravo</u> |
| Telephone: | |
| Fax: | <u>(905) 848-2827</u> |
| From: | <u>Warranty Services Department - Head Office</u> |


| Please complete the following items: | | | | |
|--------------------------------------|---|---|-----------------------|-------|
| Deficiency Number | Issue | | Appointment Date/Time | Notes |
| 10178 | LIVING/DINING ROOM- WINDOWS- ALUMINUM along top of balcony door at the ceiling, excessive gap | ✓ | | |
| 10179 | LIVING/DINING ROOM- WINDOWS: 1- ALUMINUM marked and scratched around balcony door, see tape | ✓ | | |
| 10180 | LIVING/DINING ROOM- WINDOWS: 2- CAULKING at top and right of balcony door is rough, see tape | ✓ | | |
| 10181 | LIVING/DINING ROOM- WALLS-marks, left wall, see tape | ✓ | | |
| 10182 | LIVING/DINING ROOM- WALLS: 1-paint chip corner to left of bedroom, see tape | ✓ | | |
| 10183 | MASTER BEDROOM- WALLS-right wall cracked and paint patchy, see tape | ✓ | | |
| 10184 | MASTER BEDROOM- DOORS-chip top of entrance door, see tape | ✓ | | |
| 10185 | MASTER BEDROOM- FLOORING-CLEAN CARPET | ✓ | | |
| 10187 | MASTER BEDROOM- CLOSET-DRYWALL dented, back wall, see tape | ✓ | | |
| 10188 | MASTER BEDROOM- CLOSET: 1-right corner at back drywall dented, see tape | ✓ | | |
| 10189 | MASTER BEDROOM- CLOSET: 2-2 dents in drywall just below ceiling to left of access panel | ✓ | | |
| 10190 | MASTER BEDROOM- CLOSET: 3-drywall cracked, back wall, see tape | ✓ | | |
| 10191 | MASTER BEDROOM- CLOSET: 4-drywall dented to left of door, see tape | ✓ | | |
| 10192 | MAIN BATHROOM- WALLS-drywall dented | ✓ | | |

| | | | | |
|-------|---|---|--|----------------|
| | above towel rack, see tape | ✓ | | |
| 10193 | MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape | ✓ | | |
| 10194 | MAIN BATHROOM- COUNTERTOPS-chip above toilet, see tape | ✓ | | |
| 10197 | KITCHEN- APPLIANCE-DISHWASHER should be stainless | → | | CALL WHIRLPOOL |
| 10198 | KITCHEN- WALLS-DRYWALL DENTED bulkhead above fridge | ✓ | | |
| 10199 | KITCHEN- WALLS: 1-DRYWALL DENTED bulkhead underside corner to left of microwave | ✓ | | |

Date Completed:

FEBRUARY 12, 09

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must** have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -FormsMenu

ID#

10178/10179/10180/10181/10182/10183/10184/10185/10187/10188/10189/10190/10191/10192/10193/10194/10197/10198/10199

Eve Ph 1 Lot 3010