

AMACON

LIVE WELL

Warranty Services**Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 3109
Closing Date	3109 - 3515 Kariya
Date	0000
Contact Name(s)	11Feb09
Contact Telephone#	Monica Saverino and Domenic Saverino
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:

Deficiency Number	Issue		Appointment Date/Time	Notes
10400 ✓	FOYER / ENTRY- WALLS-right wall by bathroom - black marks -see tape		✓	
10401 ✓	FOYER / ENTRY- WALLS: 1-wall facing kitchen paint touchup needed - black marks -see tape		✓	
10410 ✓	LIVING/DINING ROOM- WALLS-in hall left small wall by mirror closet doors corner edge paint touchups - see tape	- Group Assign	✓	
10411 ✓	LIVING/DINING ROOM- WALLS: 1-by kitchen entry - small right wall above baseboard scratched -see tape	- Group Assign	✓	
10412 ✓	LIVING/DINING ROOM- WALLS: 2-wall above fancoil paint rough -see tape	- Group Assign	✓	
10413 ✓	LIVING/DINING ROOM- WALLS: 3-wall right of fancoil patchy --see tape	- Group Assign	✓	
10414 ✓	LIVING/DINING ROOM- WALLS: 4-wall facing window patchy -see tape	- Group Assign	✓	
10415 ✓	GUEST BEDROOM 1- WALLS-jmould lifting rightside - see tape	- Group Assign	✓	
10416 ✓	GUEST BEDROOM 1- WALLS: 1-cracked wall below cable outlet -see tape	- Group Assign	✓	
10417 ✓	MASTER BEDROOM- WALLS-right wall dented - 2 spots -see tape	- Group Assign	✓	
10418 ✓	MASTER BEDROOM- WALLS: 1-left wall by mirror closet doors paint rough -see tape	- Group Assign	✓	
10419 ✓	MASTER BEDROOM- WALLS: 2-right wall by window paint rough and patchy -3 spots -see tape	- Group Assign	✓	
10420 ✓	MASTER BEDROOM- WALLS: 3-rough marks left of electrical panel -see tape	- Group Assign	✓	
10421 ✓	MASTER BEDROOM- DOORS-door handle not attached -see tape	- Group Assign	✓	
10422 ✓	MAIN BATHROOM- TUB-temperature control , faucet and showerhead need silicone -see tape	- Group Assign	✓	
10423	KITCHEN- ELECTRICAL/LIGHTING-GFI PLUG black	- Group Assign	✓	

	marked -see tape		✓	
10424	KITCHEN- WALLS-hole in wall left of telephone jack - see tape	- Group Assign	✓	
10426	GUEST BEDROOM 1- CLOSET-ceiling in closet not finished -see tape		—	needs studs
10428	ENSUITE BATHROOM- TUB-temperature control, faucet, and showerhead need silicon -see tape		✓	
10429	KITCHEN- FLOORING-tile scratched in front of fridge - see tape		—	mega city

Date Completed:

Feb 12/09 18

Amacon Customer Care Signature:

M. Fritz

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative **must have** this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -
Forms
Menu

ID#
 10400/10401/10410/10411/10412/10413/10414/10415/10416/10417/10418/10419/10420/10421/10422/10423/10424/10426/10428/10429
 Eve Ph 1 Lot 3109

P.S. guest bedroom ceiling needs studs