

AMACON

LIVE WELL

Warranty Services

Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 3201
Closing Date	3201 - 3515 Kariya
Date	0000
Contact Name(s)	12Feb09
Contact Telephone#	Nazime Askin
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:				
Deficiency Number	Issue		Appointment Date/Time	Notes
11405	FOYER / ENTRY- WALLS-marks along left wall, see tape	✓		
11406	FOYER / ENTRY- WALLS: 1-mark to left of closet, see tape	✓		
11407	FOYER / ENTRY- DOORS-scratches around door frame, see tape	✓		
11408	FOYER / ENTRY- FLOORING-grout needs cleaning, see tape	✓		
11410	FOYER / ENTRY- CEILING-AIR HOLES 3 feet from light fixture	✓		
11414	LIVING/DINING ROOM- ELECTRICAL/LIGHTING-light switch for outlet is by thermostat - can it be changed to opposite wall	✓		CALL DECC
11415	LIVING/DINING ROOM- ELECTRICAL/LIGHTING: 1-low air flow from vent	✓		CALL DECC
11416	LIVING/DINING ROOM- WINDOWS-window sill chipped, see tape	✓		
11417	LIVING/DINING ROOM- WINDOWS: 1-excessive silicone top of balcony door, see tape	✓		
11418	LIVING/DINING ROOM- WALLS-mark right wall to right of telephone jack, see tape	✓		
11419	LIVING/DINING ROOM- WALLS: 1-marks and dents, left wall, see tape	✓		
11420	LIVING/DINING ROOM- WALLS: 2-DRYWALL DENTED in front of kitchen island, see tape	✓		
11421	LIVING/DINING ROOM- WALLS: 3-right wall rough and paint patchy and nailpop	✓		
11422	LIVING/DINING ROOM- WALLS: 4-left wall paint patchy	✓		
11423	LIVING/DINING ROOM- WALLS: 5-hole above outlet, left wall, see tape	✓		
11424	LIVING/DINING ROOM- WALLS: 6-marks on quarter round, right wall, see tape	✓		
11425	MASTER BEDROOM- WALLS-seams showing left wall	✓		
11426	MASTER BEDROOM- WALLS: 1-mark on wall to right of closet light switch, see tape	✓		
11427	MASTER BEDROOM- WALLS: 2-crack in bulkhead by closet, see tape	✓		
11428	MASTER BEDROOM- WALLS: 3-discoloration on bulkhead by window, see tape	✓		
11429	MASTER BEDROOM- WALLS: 4-baseboard chipped right wall to right of cable outlet, see tape	✓		
11430	MASTER BEDROOM- FLOORING-CLEAN CARPET	✓		CALL IT IN
11432	MASTER BEDROOM- CEILING-mark by speaker	✓		
11433	MASTER BEDROOM- CEILING: 1-blue mark to right of air vent	✓		
11434	MASTER BEDROOM- CEILING: 2-stipple required top right window	✓		
11436	MASTER BEDROOM- CLOSET-DRYWALL discolored, see tape	✓		
11437	MASTER BEDROOM- CLOSET: 1-mark on drywall to left of door, see tape	✓		
11438	MASTER BEDROOM- CLOSET: 2-back of closet door scratched, see tape	✓		
11439	MASTER BEDROOM- CLOSET: 3-chip on front of closet door, see tape	✓		
11440	MASTER BEDROOM- ELECTRICAL/LIGHTING-fire alarm silencer scratched, see tape	✓		
11442	MAIN BATHROOM- DOORS-lock doesn't work properly	✓		
11443	MAIN BATHROOM- DOORS: 1-chip inside casing, top left corner, see tape	✓		
11444	MAIN BATHROOM- TUB-silicone around showerhead, tap, faucet, see tape	✓		
11445	MAIN BATHROOM- ELECTRICAL/LIGHTING-light fixture dented, see tape	✓		CALL DECC
11447	KITCHEN- FLOORING-paint on tiles in front of fridge, see tape	✓		
11451	KITCHEN- WALLS: 1-nailpop at bulkhead for microwave see tape	✓		
11452	LAUNDRY CLOSET- NOTE-marks on tiles, see tape	✓		
11471	KITCHEN- WALLS-DRYWALL DENTED to right of telephone jack, see tape	✓		

Date Completed:

FEBRUARY 12, 09

Amacon Customer Care Signature:

M. Fritz

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -

Forms

Menu

11405/11406/11407/11408/11410/11414/11415/11416/11417/11418/11419/11420/11421/11422/11423/11424/11425/11426/11427/11428/11429/11430/11432/11433/11434/11436/11437/11438/11439/11440/11442/11443/11444/11445/11447/11451/11452/11471

Eve Ph 1 Lot 3201