

**AMACON**

LIVE WELL

## Warranty Services

## Work Order

Phone: (905) 848-2069 Fax: (905) 848-2827

Location	Eve - Tower: 1 - Unit: 3206 3206 - 3515 Kariya
Closing Date	0000
Date	12Feb09
Contact Name(s)	Peter Luzar
Contact Telephone#	
Company:	Amacon Service
Attention:	Carlos Bravo
Telephone:	
Fax:	(905) 848-2827
From:	Warranty Services Department - Head Office

Please complete the following items:		Appointment	Notes
Deficiency Number	Issue	Date/Time	
11608	FOYER / ENTRY- WALLS-DRYWALL DENTED left wall, see tape	✓	
11609	FOYER / ENTRY- DOORS-draft coming in through left side	✓	
11610	FOYER / ENTRY- DOORS: 1-chip in door frame, see tape	✓	
11613	LIVING/DINING ROOM- WINDOWS-ALUMINUM scratched of balcony door, see tape	✓	
11614	LIVING/DINING ROOM- WINDOWS: 1-excessive gap along trim at top of balcony door and windows	✓	
11615	LIVING/DINING ROOM- WINDOWS: 2-caulking along balcony door dented/rough, see tape	✓	
11616	LIVING/DINING ROOM- WINDOWS: 3-ALUMINUM dented bottom left of balcony door, see tape	✓	
11617	LIVING/DINING ROOM- WALLS-discoloration to left of window, top corner, see tape	✓	
11618	LIVING/DINING ROOM- WALLS: 1-DRYWALL DENTED to right of air vent, see tape	✓	
11619	LIVING/DINING ROOM- WALLS: 2-discoloration above guest bedroom door at ceiling	✓	
11620	GUEST BEDROOM 1- DOORS-chip front of door lower left side, see tape	✓	
11621	GUEST BEDROOM 1- CEILING-AIR HOLES 2 feet from entry door	✓	
11622	GUEST BEDROOM 1- CLOSET-drywall tape showing on ceiling in front of door	✓	
11623	GUEST BEDROOM 1- WINDOWS-ALUMINUM frame scratched, see tape	✓	
11625	MASTER BEDROOM- WALLS-paint on J-mold top left window	✓	
11627	MASTER BEDROOM- ELECTRICAL/LIGHTING-breakers recessed too far need to be realigned	✓	
11628	MASTER BEDROOM- WINDOWS-paint overspray top left window, see tape	✓	
11629	MASTER BEDROOM- WINDOWS: 1-balcony sill scratched, see tape	✓	
11630	MAIN BATHROOM- WALLS: 1-DRYWALL blem. left of sink, see tape	✓	
11631	MAIN BATHROOM- WALLS-DRYWALL DENTED above towel rack, right side, see tape	✓	
11632	MAIN BATHROOM- TUB-silicone around showerhead, tap and faucet, see tape	✓	
11633	MAIN BATHROOM- TUB: 1-showerhead not secure properly	✓	
11634	MAIN BATHROOM- TOILET-toilet not perpendicular to wall	✓	
11636	MAIN BATHROOM- TOILET: 1-tank lid scratched, see tape	✓	
11637	MAIN BATHROOM- CEILING-splatter on ceiling above towel rack	✓	
11638	MAIN BATHROOM- SINK-plumbing coming from wall is loose	✓	call us!
11639	ENSUITE BATHROOM- WALLS-mark on wall opposite toilet, below towel bar, see tape	✓	
11640	ENSUITE BATHROOM- DOORS-gaps upper corners of casing inside and out, see tape	✓	
11641	ENSUITE BATHROOM- DOORS: 1-dent on outside of door, left side, see tape	✓	
11642	ENSUITE BATHROOM- TUB-silicone around showerhead, tap and faucet, see tape	✓	
11643	ENSUITE BATHROOM- TUB: 1-showerhead not properly secured	✓	
11646	ENSUITE BATHROOM- SINK-plumbing coming from wall is loose	✓	call us!
11647	ENSUITE BATHROOM- VANITY CABINETS-access panel door inside vanity cabinet is off/not installed	✓	
11649	KITCHEN- APPLIANCE-paint on dishwasher door, right side, see tape	✓	
11650	KITCHEN- APPLIANCE: 1-scratch on fridge door, see tape	✓	
11651	LAUNDRY CLOSET- NOTE-mark on floor right of washer, see tape	✓	
11652	LAUNDRY CLOSET- DOORS-chip in door side, see tape	✓	

Date Completed:

FEBRUARY 13, 09 8

Amacon Customer Care Signature:

Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827.

Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back-

Forms

Menu

ID#

11608/11609/11610/11613/11614/11615/11616/11617/11618/11619/11620/11621/11622/11623/11625/11627/11628/11629/11630/11631/11632/11633/11634/11636/11637/11638/11639/11640/11641/11642/11643/11646/11647/11649/11650/11651/11652

Eve Ph 1 Lot 3206