

**AMACON**

LIVE WELL

**Warranty Services  
Work Order**

Phone: (905) 848-2069 Fax: (905) 848-2827

<b>Location</b>	<b>Eve - Tower: 1 - Unit: 3603</b> <b>3603 - 3515 Kariya</b>
<b>Closing Date</b>	<b>0000</b>
<b>Date</b>	<b>31Mar09</b>
<b>Contact Name(s)</b>	<b>Michelle Sue and Mark Harris</b>
<b>Contact Telephone#</b>	
<b>Company:</b>	<b>Amacon Service</b>
<b>Attention:</b>	<b>Carlos Bravo</b>
<b>Telephone:</b>	
<b>Fax:</b>	<b>(905) 848-2827</b>
<b>From:</b>	<b>Warranty Services Department - Head Office</b>

Please complete the following items:			
Deficiency Number	Issue	Appointment Date/Time	Notes
12593	FOYER / ENTRY- WALLS-marks below light switch to right of door, seeTAPE		
12594	FOYER / ENTRY- WALLS: 1-DRYWALL cracked and pinholes to left of door, seeTAPE		
12595	FOYER / ENTRY- WALLS: 2-mark to right of closet, seeTAPE		
12596	FOYER / ENTRY- DOORS-paint above door handle and flecks of paint all over, seeTAPE		
12597	FOYER / ENTRY- DOORS: 1-door not varnished		
12598	FOYER / ENTRY- DOORS: 2-frame scratched along top and bottom right side, seeTAPE		
12599	FOYER / ENTRY- FLOORING-paint on tile to left of door, seeTAPE		
12600	FOYER / ENTRY- CLOSET-closet doors squeaky		
12601	FOYER / ENTRY- CLOSET: 1-paint on tiles inside, seeTAPE		
12607	LIVING/DINING ROOM- WINDOWS: 1-ALUMINUM scratched, seeTAPE		
12608	GUEST BEDROOM 1- DOORS-door cracked by latch, seeTAPE		
12609	GUEST BEDROOM 1- DOORS: 1-casing chipped inside, see tape		
12610	GUEST BEDROOM 1- FLOORING-CLEAN CARPET		
12612	GUEST BEDROOM 1- ELECTRICAL/LIGHTING-telephone jack missing		
12613	GUEST BEDROOM 2- WALLS-mark on right wall below breaker panel, seeTAPE		
12614	GUEST BEDROOM 2- WALLS: 1-chip on corner to left of breaker panel, seeTAPE		
12615	GUEST BEDROOM 2- WALLS: 2-chips to left of closet, see tape		
12616	GUEST BEDROOM 2- FLOORING-CLEAN CARPET		
12617	GUEST BEDROOM 2- FLOORING: 1-crack on baseBOARD to left of closet, seeTAPE		
12618	GUEST BEDROOM 2- CLOSET-paint on valance, seeTAPE		
12621	GUEST BEDROOM 2- WINDOWS-ALUMINUM THRESHOLD loose, seeTAPE		
12624	MASTER BEDROOM- WALLS-crack in bulkhead to left of sliding door		
12625	MASTER BEDROOM- WALLS: 1-mark to left of walk-in closet, see tape		
12626	MASTER BEDROOM- WALLS: 2-excessive paint drip to left of ensuite, see tape		
12627	MASTER BEDROOM- WALLS: 3-DRYWALL DENTED top right corner of sliding closet, seeTAPE		
12628	MASTER BEDROOM- WALLS: 4-marks/chips to right of walk-in closet, seeTAPE		
12629	MASTER BEDROOM- WALLS: 5-marks on wall opposite window, see tape		
12630	MASTER BEDROOM- WALLS: 6-marks right wall below THERMOSTAT, seeTAPE		
12631	MASTER BEDROOM- WALLS: 7-marks on left wall, seeTAPE		
12632	MASTER BEDROOM- WALLS: 8-marks on right wall in front of window, seeTAPE		
12633	MASTER BEDROOM- DOORS-casing chipped all around, seeTAPE		
12634	MASTER BEDROOM- DOORS: 1-chips front of door between hinges, seeTAPE		
12635	MASTER BEDROOM- FLOORING-CLEAN CARPET		
12636	MASTER BEDROOM- FLOORING: 1-BASEBOARD scratched left side, see tape		
12637	MASTER BEDROOM- CLOSET-clean carpet inside walk-in closet		
12638	MASTER BEDROOM- CLOSET: 1-walk-in door handles scratched, seeTAPE		
12639	MASTER BEDROOM- CLOSET: 2-walk-in closet door doesn't close properly		
12640	MASTER BEDROOM- CLOSET: 3-casing chipped inside and outside of walk-in closet, seeTAPE		
12641	MASTER BEDROOM- CLOSET: 4-chip on walk-in closet door between hinges, seeTAPE		
12642	MASTER BEDROOM- CLOSET: 5-mark on wall opposite door of walk-in closet, seeTAPE		
12643	MASTER BEDROOM- CLOSET: 6-mark on back wall of sliding closet, seeTAPE		
12644	MASTER BEDROOM- CLOSET: 7-dryWALL dented inside sliding closet, see tape		
12647	MASTER BEDROOM- ELECTRICAL/LIGHTING: 1-THERMOSTAT controls don't move		
12648	MASTER BEDROOM- WINDOWS-BALCONY SILL seam showing to right of balcony door, seeTAPE		
12649	DEN- WALLS-DRYWALL DENTED right wall, seeTAPE		
12650	DEN- FLOORING-scuff mark and scratches, see tape		
12651	DEN- ELECTRICAL/LIGHTING-telephone jack missing		

12652	MAIN BATHROOM- TUB-stopper not working			
12653	MAIN BATHROOM- CEILING-discoloration at front of tub			
12654	MAIN BATHROOM- COUNTERTOPS-mark on backSPLASH, seeTAPE			
12655	MAIN BATHROOM- COUNTERTOPS: 1-caulking required top of backSPLASH below outlet, seeTAPE			
12656	MAIN BATHROOM- FLOORING-paint on tiles see tape			
12657	MAIN BATHROOM- ELECTRICAL/LIGHTING-BULBS BURNED OUT			
12658	ENSUITE BATHROOM- DOORS-chipped casing back of door, right side, see tape			
12659	ENSUITE BATHROOM- DOORS: 1-caulking cracked along right side of door, see tape			
12660	ENSUITE BATHROOM- DOORS: 2-casing chipped inside above striker plate, seeTAPE			
12661	ENSUITE BATHROOM- DOORS: 3-outside casing chipped, left side, see tape			
12662	ENSUITE BATHROOM- DOORS: 4-outside casing chipped, right side, seeTAPE			
12663	ENSUITE BATHROOM- DOORS: 5-gaps at topcasing corners, seeTAPE			
12664	ENSUITE BATHROOM- TUB-paint top left and right glass panels, see tape			
12665	ENSUITE BATHROOM- TUB: 1-mark left glass panel, see tape			
12666	ENSUITE BATHROOM- TUB: 2-ceiling discolored front corner			
12667	ENSUITE BATHROOM- TUB: 3-caulking around top of stall very uneven			
12671	ENSUITE BATHROOM- TUB: 6-aluminum to left of shower door not flush, needs more silicone, see tape			
12672	ENSUITE BATHROOM- TUB: 7-caulking required top of aluminum pst to left of shower door, seeTAPE			
12673	ENSUITE BATHROOM- CEILING-mark on ceiling to right of exhaust fan, see tape			
12691	KITCHEN- COUNTERTOPS-wrong countertop should be from package A not C			
12692	KITCHEN- COUNTERTOPS: 1-excessive gap below countertop, and above cabinet			
12693	KITCHEN- APPLIANCE-dishwasher not flush			
12694	KITCHEN- APPLIANCE: 1-scratch on stove handle, seeTAPE			
12695	LAUNDRY CLOSET- DOORS-inside door scratched at top and centre pnael, see tape			
12696	LAUNDRY CLOSET- WALLS-mark on right wall, seeTAPE			

Date Completed:

march 23/07

Amacon Customer Care Signature:



Please schedule your Service Department to complete work on the above Unit. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 848-2827. Failure to comply with this request will give Amacon Developments (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Back -

Forms

Menu

12593/12594/12595/12596/12597/12598/12599/12600/12601/12607/12608/12609/12610/12612/12613/12614/12615/12616/12617/12618/12621/12624/12625/12626/12627/12628/12629/12630/12631/